

### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

Completed December 1-9, 2014

#### Recommendation Categories

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.●	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
1-Y	Tags 1-217 are Yellow tape tags	<i>Acer platanoides</i>	Norway Maple	31 cm	Good	Good	X		D
2-Y		<i>Acer platanoides</i>	Norway Maple	28.5 cm	Good	Good	X		A
3-Y		<i>Picea pungens</i>	Spruce	45 cm	Good	Good	X		A
4-Y		<i>Picea abies</i>	Norway Spruce	50cm	Good	Good	X		A
5-Y		<i>Pinus nigra</i>	Austrian Pine	48 cm	Good	Good	X		A
6-Y		<i>Pinus nigra</i>	Austrian Pine	42.5 cm	45% dead	Poor	X		B
7-Y		<i>Pinus nigra</i>	Austrian Pine	30.5cm	70% Dead	Poor	X		B
8-Y		<i>Picea pungens</i>	Spruce	29.5 cm	Good- Remove lower branches	Good	X		D
9-Y		<i>Picea Spl</i>	Spruce	32.5cm	20% Dead- prune lower dead branches	Good	X		D
10-Y		<i>Picea Sp.</i>	Spruce	32.5 cm	Good- Retain as part of grouping	Good	X		D
11-Y		<i>Pinus sylvestris</i>	Scots Pine	24.5 cm	Branching determined by group	Good	X		D
12-Y		<i>Pinus nigra</i>	Austrian Pine	20, 37.5cm	2 stem, needs pruning- retain as part of group	Fair	X		D
13-Y		<i>Pinus nigra</i>	Austrian Pine	37.5cm	Fair, Prune out dead material- retain as part of group	Fair	X		D
14-Y		<i>Pinus nigra</i>	Austrian Pine	32.5cm	Prune out dead material- retain as part of g	Fair	X		D
15-Y		<i>Gleditsia triacanthos</i>	Honeylocust	30cn	Badly pruned due to adjacent power lines- retain as part of group	Fair	X		D

Table 1

### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.●	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
16-Y		<i>Populus sp.</i>	Poplar	59 cm	On adjacent property	Good	X		C
17-Y		<i>Populus sp.</i>	Poplar	57.5 cm	On adjacent property	Good	X		C
18-Y		<i>Thuja</i>	Easter White Cedar	n.a.	Hedge- straddles property?	Good	X		C
19-Y		<i>Pinus strobus</i>	Eastern White Pine	27 cm	located in hedge on adjacent property?	Good	X		C
20-Y		<i>Thuja</i>	Cedar Grouping	6 stem <20cm	multiple trunk	Good	X		D
21-Y		<i>Pinus sylvestris</i>	Scots Pine	22 cm	Lower branches dead	Good	X		D
22-Y		<i>Acer platanoides</i>	Norway Maple	28 cm	Good	Good	X		D
23-Y		<i>Acer Sp.</i>	Maple	24, 50 cm	Co dominant multi trunk	Good	X		D
24-Y		<i>Acer sp.</i>	Maple	29.5 cm	Good- Off property?	Good	X		C
25-Y		<i>Pinus sylvestris</i>	Scots Pine	30.5 cm	70% Dead	Poor	X		C
26-Y		<i>Fraxinus pensylvanica</i>	Green Ash	35.5 cm	60% Dead	Poor	X		B
27-Y		<i>Acer platanoides</i>	Norway Maple	28.5 cm	Good- Off property?	Good	X		C
28-Y		<i>Picea sp.</i>	Spruce	22.5 cm	Good- Off property?	Good	X		C
29-Y		<i>Acer</i>	Maple	24, 24 cm	Co dominant multi trunk	Fair	X		D
30-Y		<i>Populus sp.</i>	Poplar	56 cm	Good- Off property?	Good	X		C

Table 1

## TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.●	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
31-Y		<i>Populus sp.</i>	Poplar	60cm	Good-Off Property?	Good	X		C
32-Y		<i>Thuja sp.</i>	Cedar	<20cm	Multi trunk large specimen- beautiful	Good	X		D
33-Y		<i>Thuja sp.</i>	Cedar	<20cm	Multi trunk large specimen- beautiful	Good	X		A
34-Y		<i>Populus sp.</i>	Poplar	46.5 cm	Part of naturalized area	Good	X		C
35-Y		<i>Populus sp.</i>	Poplar	66cm	Part of naturalized area	Good	X		D
36-Y		<i>Tilia cordata</i>	Linden	30.5 cm	Remove suckers at base	Good	X		A
37-Y		<i>Tilia cordata</i>	Linden	29.5 cm	Remove suckers at base	Good	X		A
38-Y		<i>Tilia cordata</i>	Linden	28.5 cm	Remove suckers at base	Good	X		A
39-Y		<i>Tilia cordata</i>	Linden	30.5 cm	Becomes codominant	Good	X		A
40-Y		<i>Acer platanoides</i>	Norway Maple	25 cm	Good	Good	X		A
41-Y		<i>Tilia cordata</i>	Linden	29.5 cm	Good- suckers	Good	X		A
42-Y		<i>Tilia cordata</i>	Linden	40.5 cm	Becomes codominant	Good	X		A
43-Y		<i>Acer platanoides</i>	Maple	29 cm	Central leader dead. Bark skinned	Poor		X	B
44-Y		<i>Picea</i>	Spruce	57 cm	Good	Good	X		A
45-Y		<i>Picea</i>	Spruce	39.5 cm	Good	Good	X		A

Table 1

## TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.)	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name	D.B.H.•			High	Low	
46-Y		<i>Picea sp.</i>	Spruce	46 cm	Good	Good	X		A
47-Y		<i>Picea sp.</i>	Spruce	57.5 cm	Good	Good	X		A
48-Y		<i>Picea sp.</i>	Spruce	38.5 cm	Good	Good	X		D
49-Y		<i>Picea sp.</i>	Spruce	42 cm	Good- surrounded by buckthorn	Good	X		A
50-Y		<i>Acer negundo</i>	Manitoba Maple	16, 24 cm	Co dominant,	Good		X	D
51-Y		<i>Populus sp.</i>	Poplar	80 cm	Good	Good	X		C
52-Y		<i>Pinus sp.</i>	Pine	21.5cm	Dead	Poor		X	B, C
53-Y		<i>Acer platanoides</i>	Maple	17, 27 cm	Co dominant, crossing branches	Fair	X		D
54-Y		<i>Malus sp.</i>	Apple	35 cm	Crossing trunks, thorny	Fair	X		D
55-Y		<i>Malus sp.</i>	Apple	29,29,23,24,12	5 trunk multi stem crossing	Fair		X	D
56-Y		<i>Acer platanoides</i>	Maple	22 cm	Bark loss on leader some dieback	Fair		X	D
57-Y		<i>Acer</i>	Maple	22 cm	Co dominant- some twing die back	Fair		X	D
58-Y		<i>Acer</i>	Maple	14, 22 cm	2 stem multi	Good	X		D
59-Y		<i>Malus sp.</i>	Apple	42 cm	bark loss on portions, branch and twig dieback	Fair		X	D
60-Y		<i>Malus sp.</i>	Apple	29 cm	Bark missing	Fair		X	D

Table 1

## TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.°	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
61-Y		<i>Malus sp.</i>	Apple	20,20,16, 16.5 cm	4 trunk Multi speciment, some die back	Fair		X	D
62-Y		<i>Populus sp.</i>	Poplar	27.5 cm	Good	Good	X		D
63-Y		<i>Acer sp.</i>	Maple	16, 12,15 cm	3s tem multi trunk	Good	X		D
64-Y		<i>Pinus sp.</i>	Pine	54,21,36 cm	Dead	Poor		X	B
65-Y		<i>Malus sp.</i>	Apple	26,15 cm	2 trunk lots of dead in wooded area	Fair		X	D
66-Y		<i>Acer negundo</i>	Manitobal Maple	57, 28,36.5,42 cm	4 trunk mulit speimen	Good	X		D
67-Y		<i>Malus sp.</i>	Apple	32.5 cm	Good	Good	X		D
68-Y		<i>Malus sp.</i>	Apple	37,41,46,49 cm	4 trunk mulit trunk specimen, cavities, conks, mushrooms	Good	X		D
69-Y		<i>Tsuga canadensis</i>	Hemlock	100 cm	Top dead, holes in trunk- in wooded area	Poor		X	B
70-Y		<i>Tsuga canadensis</i>	Hemlock	37.5 cm	lower dead branches- in wooded area	Good	X		D
71-Y		<i>Tsuga canadensis</i>	Hemlock	67,82 cm	2 trunk multi form- in wooded area	Good	X		D
72-Y		<i>Acer plat</i>	Maple	30cm	Good	Good	X		D
73-Y		<i>Tsuga canadensis</i>	Hemlock	24.5 cm	Good	Good	X		D
74-Y		<i>Tsuga canadensis</i>	Hemlock	60cm	Awkward Form	Good	X		D
75-Y		<i>Tsuga canadensis</i>	Hemlock	76 cm	Good- forest branched	Good	X		D

Table 1

## TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.●	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
76-Y		<i>Tsuga canadensis</i>	Hemlock	52 cm	Good- Forest branched	Good	X		D
77-Y		<i>Acer negundo</i>	Manitoba Maple	27 cm	Poor form, no leader	Fair		X	D
78-Y		<i>Tsuga canadensis</i>	Hemlock	67 cm	Good- Forest branched	Good	X		D
79-Y		<i>Thuja</i>	White Cedar Clump	30,21,28, 5<20cm	8 trunk Clump good	Good	X		D
80-Y		<i>Thuja</i>	White Cedar Clump	20,16,18,19,2	5 trunk clump Good	Good	X		D
81-Y		<i>Thuja</i>	White Cedar Clump	32,16,21,14,18	5 trunk clump Good	Good	X		D
82-Y		<i>Thuja</i>	White Cedar Clump	28,23,27	3 trunk clum Good	Good	X		D
83-Y		<i>Tsuga canadensis</i>	Hemlock	31.5cm	Dead wood	Fair	X		D
84-Y		<i>Picea sp.</i>	Spruce	36.5 cm	Good	Good	X		D
85-Y		<i>Acer platanoides</i>	Norway Maple	28,31 cm	Co-dominant	Good	X		D
86-Y		<i>Malus sp.</i>	Apple	23,27,34 cm	Broken limbs, hollows	Fair	X		D
87-Y		<i>Malus sp.</i>	Apple	26,32,14 cm	Broken limbs, hollows, overgrown	Fair	X		D
88-Y		<i>Malus sp.</i>	Apple	20,29 cm	Broken limbs, hollows	Fair	X		D
89-Y		<i>Picea sp.</i>	Spruce	45 cm	Good	Good	X		D
90-Y		<i>Acer sp.</i>	Maple	32 cm	Poor structure, dead branches	Fair	X		D

Table 1

### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.•	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
91-Y		<i>Acer platanoides</i>	Maple	39.5 cm	Good	Good	X		D
92-Y		<i>Tsuga canadensis</i>	Hemlock	25,29cm	2 trunk specimen	Good	X		D
93-Y		<i>Pinus strobus</i>	White Pine	35,28 cm	2 trunk specimen	Good	X		D
94-Y		<i>Fraxinus sp.</i>	Ash	43 cm	Poor form, dead branches	Fair	X		D
95-Y		<i>Acer platanoides</i>	Maple	31 cm	Good	Good	X		D
96-Y		<i>Thuja</i>	Cedar	28 cm	Cedar clump	Good	X		D
97-Y		<i>Malus sp.</i>	Apple	42,21,26cm	Retain as part of clump	Good	X		D
98-Y		<i>Acer sp.</i>	Maple	41 cm	Good	Good	X		D
99-Y		<i>Acer sp.</i>	Maple	31.5 cm	Good	Good	X		D
100-Y		<i>Gleditsia triacanthos</i>	Honeylocust	33cm	Good	Good	X		D
101-Y		<i>Fraxinus sp.</i>	Ash	39cm		Fair	X		D
102-Y		<i>Fraxinus sp.</i>	Ash	40 cm	Fair	Fair	X		D
103-Y		<i>Fraxinus sp.</i>	Ash	36cm	Fair	Fair	X		D
104-Y		<i>Pinus sylvestris</i>	Scots Pine	33.5cm	Good	Good	X		D
105-Y		<i>Thuja</i>	Cedar	30.5 cm	Clump retain as whole	Good	X		D

### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.♦	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
106-Y		<i>Malus sp.</i>	Apple	28.5 dm	As part of clump of vegetation	Fair		X	D
107-Y		<i>Malus sp.</i>	Apple	32 cm	Hollows, wounds on trunk	Poor		X	D
108-Y		<i>Acer sp.</i>	Maple	46 cm	Good	Good	X		D
109-Y		<i>Acer sp.</i>	Maple	32 cm	Good	Good	X		A
110-Y		<i>Thuja</i>	Cedar clump	34,32,14,12,18cm	5 trunk specimen	Good	X		A
111-Y		<i>Thuja</i>	Cedar clump	38,28,17 cm	3 trunk specimen	Good	X		A
112-Y		<i>Thuja</i>	Cedar Clump	37,14,29,22 cm	4 trunk specimen	Good	X		A
113-Y		<i>Thuja</i>	Cedar Clump	28,32,30cm	3 trunk specimen	Good	X		A
114-Y		<i>Thuja</i>	Cedar clump	28,30,20,19,14cm	5 trunk specimen	Good	X		A
115-Y		<i>Thuja</i>	Cedar clump	25,23,20,19,21 cm	5 trunk specimen	Good	X		A
116-Y		<i>Thuja</i>	Cedar clump	21,22,24,16 cm	4 trunk specimen	Good	X		A
117-Y		<i>Thuja</i>	Cedar clump	10 trunks <20cm	Multi trunk specimen	Good	X		A
118-Y		<i>Thuja</i>	Cedar clump	34,23,22,19,20,14 cm	6 trunk specimen	Good	X		A
119-Y		<i>Picea pungens</i>	Spruce	52 cm	Good	Good	X		A
120-Y		<i>Picea sp.</i>	Spruce	33 cm	Good	Good	X		A



### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.●	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
121-Y		<i>Acer</i>	Maple	31.5 cm	Good	Good	X		A
122-Y		<i>Thuja</i>	Cedar Hege	4 trunks <20cm	Good	Good	X		A
123-Y		<i>Pinus nigra</i>	Austrian Pine	39.5 cm	40% dead, needles yellowed	Poor		X	A
124-Y		<i>Thuja</i>	Cedar Hege	20 trunks <20cm	Good	Good	X		A
125-Y		<i>Populus???</i>	Poplar???	46.5cm	Mostl dead, pruned to remove hazard limbs	Poor		X	A
126-Y		<i>Tilia</i>	Linden	47.5 cm	Good	Good	X		A
127-Y		<i>Acer plat.</i>	Maple	29.5 cm	Badly damaged trunk	Fair		X	A
128-Y		<i>Thuja</i>	Cedar Clump	7 trunk <20cm	7 trunk specimen	Good	X		A
129-Y		<i>Thuja</i>	Cedar Clump	8 trunk 22cm, 7 <20cm	8 trunk specimen	Good	X		A
130-Y		<i>Tilia cordata</i>	Linden	23,23,25 cm	3 trunk co-dominant	Good	X		A
131-Y		<i>Thuja</i>	Cedar Clump	11 trunk <20cm	11 trunk clump cedar	Good	X		A
132-Y		<i>Thuja occidentali</i>	Cedar Clump	13 trunk <20cm	13 trunk cedar	Good	X		A
133-Y		<i>Thuja</i>	Cedar Clump	21cm, 11<20cm	12 trunk cedar, 1 >20cm, 11<20cm	Good	X		A
134-Y		<i>Acer plat.</i>	Maple	23.5,21.5cm	Multiple wounds on trunk, stripped bark	Poor		X	A
135-Y		<i>Thuja</i>	Cedar Clump	25cm, 7<20cm	8 trunk multi specimen, 1@25cm, 7<20cm	Good	X		A

**TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY**

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.*	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
136-Y		<i>Ulmus sp.</i>	Elm	50cm	Stumped limbs, poorly pruned	Fair		x	A
137-Y		<i>Ulmus sp.</i>	Elm	46cm	Stumped limbs, poorly pruned	Fair		x	A
138-Y		<i>Fraxinus</i>	Ash	25cm	Good	Fair	X		D
139-Y		<i>Pinus nigra</i>	Austrian Pine	39cm	Good	Good	X		D
140-Y		<i>Acer saccharinum</i>	Silver Maple	53cm	Good	Good	X		D
141-Y		<i>Fraxinus</i>	Ash	37cm	Fair	Fair	X		D
142-Y		<i>Pinus strobus</i>	White Pine	20cm	Good	Good	X		D
143-Y		<i>Populus</i>	Poplar	36cm	Good	Good	X		D
144-Y		<i>Thuja hedge</i>	Cedar Hedge	multi trunk <20cn	Good	Good	X		D
145-Y		<i>Acer sp.</i>	Maple	25,15,6,63	4 trunk	Good	X		D
146-Y		<i>Fraxinus</i>	Ash	46 cm	Good	Fair	X		A
147-Y		<i>Malus spl</i>	Apple	21,22,12,16	Multi trunk low branching species	Good	X		A
148-Y		<i>Fraxinus</i>	Ash	26cm	Good	Good	X		A
149-Y		<i>Acer plat.</i>	Maple	28.5cm	Good	Good	X		A
150-Y		<i>Ulmus sp.</i>	Elm	39.5cm	Good	Good	X		A

### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.●	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
151-Y		<i>Acer</i>	Maple	20,23 cm	Trunk becomes co-dominant @1.0m high	Good	X		A
152-Y		<i>Populus</i>	Poplar	53.5cm	Good	Good	X		A
153-Y		<i>Populus</i>	Poplar	72cm	Good	Good	X		A
154-Y		<i>Acer plat.</i>	Norway Maple	36cm	Patches of bark falling, needs pruning	Good	X		A
155-Y		<i>Acer platanoides</i>	Norway Maple	37.5cm	limb cracked	Good	X		D
156-Y		<i>Thuja</i>	Cedar Clump	24,25,12,19,9	5 trunk clump	Good	X		D
157-Y		<i>Picea</i>	Spruce	23cm	Part of a row of trees	Good	X		D
158-Y		<i>Picea</i>	Spruce	23cm	Part of a row of trees	Good	X		D
159-Y		<i>Thuja</i>	Cedar Clump	multi trunk <20cm	multi trunk clump. 9 stems <20cm	Good	X		D
160-Y		<i>Thuja</i>	Cedar Clump	6,9,4,21,18cm	multi trunk clump. 5 stems	Good	X		D
161-Y		<i>Picea</i>	Spruce	39cm	Part of a row of trees	Good	X		D
162-Y		<i>Thuja</i>	Cedar Clump	20,19,12,10	multi trunk clump, 5 stem	Good	X		D
163-Y		<i>Picea</i>	Spruce	39cm	Retain as part of row of trees	Good	X		D
164-Y		<i>Thuja occidentalis</i>	Cedar Clump	27,21.5,12,20cm	multi trunk clump, 4 stem	Good	X		D
165-Y		<i>Picea</i>	Spruce	40cm	Retain as part of row of trees	Good	X		D

### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.*	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
166-Y		<i>Picea</i>	Spruce	55cm	Good	Good	X		D
167-Y		<i>Picea</i>	Spruce	35cm	Good	Good	X		D
168-Y		<i>Catalpa bignonioides</i>	Catalpa	59cm	knots, cavities, conks and fungus on tree	Fair		X	B
169-Y		<i>Picea</i>	Spruce	48cm	Good	Good		X	D
170-Y		<i>Acer sp.</i>	Maple	31.5cm	Good	Good	X		D
171-Y		<i>Acer sp.</i>	Maple	44cm	Good	Good	X		D
172-Y		<i>Acer sp.</i>	Maple	24,27cm	Becomes co-dominant at approx. 1m	Good	X		D
173-Y		<i>Picea pungens glauca</i>	Blue Spruce	28 cm	Good	Good	X		D
174-Y		<i>Acer sp.</i>	Maple	32cm	Good	Good	X		D
175-Y		<i>Picea pungens glauca</i>	Blue Spruce	33cm	Good	Good	X		D
176-Y		<i>Populus</i>	Poplar	48cm	Good	Good	X		D
177-Y		<i>Populus</i>	Poplar	75cm	Good	Good	X		D
178-Y		<i>Populus</i>	Poplar	67.5cm	Good	Good	X		D
179-Y		<i>Salix pendula</i>	Weeping Willow	72.5cm	Good	Good	X		D
180-Y		<i>Thuja occidentalis</i>	Cedar Clump	31.5,41,36cm	multi trunk clump, 3 stem	Good	X		D

### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.●	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
181-Y		<i>Thuja occidentalis</i>	Cedar Clump	10,16,44,33,46,40cm	multi trunk clump, 6 trunk	Good	X		D
182-Y		<i>Thuja occidentalis</i>	Cedar Clump	24,33,38,46,32,30cm	multi trunk clump, 6 trunk	Good	X		A
183-Y		<i>Thuja occidentalis</i>	Cedar Clump	30,33,38,32,36,12,31,33,4<20cm	Multi trunk clump,12 trunk	Good	X		A
184-Y		<i>Thuja occidentalis</i>	Cedar Clump	20,14,12,15,15,20,19,14,several <20cm	Multi trunk clump, 40 trunk	Good	X		A
185-Y		<i>Thuja occidentalis</i>	Cedar Clump	38,40,33,22cm	Good	Good	X		A
186-Y		<i>Thuja occidentalis</i>	Cedar Clump	55cm, 4 trunks <20cm	Good	Good	X		A
187-Y		<i>Thuja occidentalis</i>	Cedar Clump	32,30,6,8,21cm	Good	Good	X		A
188-Y		<i>Malus sp.</i>	Apple	32,33,30	Good	Good	X		A
189-Y		<i>Pinus sylvestris</i>	Scot's Pine	27.5cm	Growth, Conks, dieback	Fair		X	A
190-Y		<i>Crataegus sp.</i>	Hawthorne	22,16,20cm	multi trunk, some hollow	Good	X		A
191-Y		<i>Thuja occidentalis</i>	Cedar Clump	28,19,21,14cm	Good	Good	X		A
192-Y		<i>Thuja occidentalis</i>	Cedar Clump	7,23,36,12,12,33,	Good	Good	X		A
193-Y		<i>Thuja occidentalis</i>	Cedar Clump	38,37,30cm	Good	Good	X		A
194-Y		<i>Thuja occidentalis</i>	Cedar Clump	9,9,11,32,30,3cm	multi trunk clump, 6 stem	Good	X		A
195-Y		<i>Thuja occidentalis</i>	Cedar Clump	42,28,35cm	multi trunk clump, 3 stem	Good	X		A

### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.●	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
196-Y		<i>Thuja occidentalis</i>	Cedar Clump	31,23,27	multi trunk clump, 3 trunk	Good	X		A
197-Y		<i>Thuja occidentalis</i>	Cedar Clump	28,28,27,22,9,19	multi trunk clump, 6 trunk	Good	X		A
198-Y		<i>Thuja occidentalis</i>	Cedar Clump	36,17,19,18,26,17	Multi trunk clump,6 trunk	Good	X		A
199-Y		<i>Thuja occidentalis</i>	Cedar Clump	33,20,24,19,14,22,29,12cm	Multi trunk clump,8 trunk	Good	X		A
200-Y		<i>Thuja occidentalis</i>	Cedar Clump	20,14,14,16,21,21,10,10,19,21	Multi trunk clump 10 trunk	Good	X		A
201-Y		<i>Thuja occidentalis</i>	Cedar Clump	23,26,16,21,15,17 cm	Multi trunk clump 6 stem	Good	X		A
202-Y		<i>Thuja occidentalis</i>	Cedar Clump	22,24,22,28,19cm	Multi trunk clump 5 stem	Good	X		A
203-Y		<i>Picea</i>	Spruce	22cm	Good	Good	X		A
204-Y		<i>Picea</i>	Spruce	19cm	Relocate if possible	Fair		X	A
		<i>Picea</i>	Spruce	16,18,19cm	3 trees between trees no. 203,204 too small to tag.	Good	X		A
205-Y		<i>Tilia sp.</i>	Linden	27cm	Becomes co-dominant suckers need to be removed	Good	X		A
206-Y		<i>Acer sp.</i>	Maple	35.5cm	Wound on trunk, healed but deep	Fair	X		A
207-Y		<i>Picea</i>	Spruce	20cm	Retain in place or relocate if possible	Good	X		A
208-Y		<i>Pinus nigra</i>	Austrian Pine	42cm	Good	Good	X		A
209-Y		<i>Acer sp.</i>	Maple	34cm	Good	Good	X		A

### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.●	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
210-Y		<i>Malus sp.</i>	Apple	25,28,33 cm	multi trunk clump, 3 trunk	Good	X		A
211-Y		<i>Acer saccharinum</i>	Silver Maple	28,27,27,36,17,21,12,17	Mult trunk, 11 trunk clump. 3 trunks <20cm	Good	X		A
212-Y		<i>Acer saccharinum</i>	Silver Maple	56cm	Good	Good	X		A
213-Y		<i>Acer saccharinum</i>	Silver Maple	32cm	Tree is leaning,	Fair	X		A
214-Y		<i>Thuja occidentalis</i>	Cedar Clump	21,23,9,3,17,7,19	Multi trunk clump 7 trunk	Good	X		A
215-Y		<i>Thuja occidentalis</i>	Cedar Clump	23,21,18,22	Multi trunk clump 4 trunk	Good	X		A
216-Y		<i>Thuja occidentalis</i>	Cedar Clump	12,16,11,16,20,18,11cm	Multi trunk clump 7 trunk	Good	X		A
217-Y		<i>Thuja occidentalis</i>	Hedge	8 trunks<20cm	8 clumps form hedge	Good	X		A
	Tree 1 in hedge	<i>Thuja occidentalis</i>	Cedar Clump	20,21,16,13,26,11 cm	6 trunk multi trunk specimen- retain as hedge	Good	X		A
	Tree 2 in hedge	<i>Thuja occidentalis</i>	Cedar Clump	16,21,19,6,14,22,23,19,8 cm	9 trunk multi trunk specimen- retain as hedge	Good	X		A
	Tree 3 in hedge	<i>Thuja occidentalis</i>	Cedar Clump	29,28,27,22 cm	4 trunk multi trunk specimen- retain as hedge	Good	X		A
	Tree 4 in hedge	<i>Thuja occidentalis</i>	Cedar Clump	28,9,19,18,26,7,9,24,26,23 cm	10 trunk multi trunk specimen- retain as hedge	Good	X		A
	Tree 5 in hedge	<i>Thuja occidentalis</i>	Cedar Clump	43,38 cm	2 trunk multi trunk specimen- retain as hedge	Good	X		A
	Tree 6 in hedge	<i>Thuja occidentalis</i>	Cedar Clump	41,43,11 cm	3 trunk multi trunk specimen- retain as hedge	Good	X		A
	Tree 7 in hedge	<i>Thuja occidentalis</i>	Cedar Clump	21,21,42,32 cm	4 trunk multi trunk specimen- retain as hedge	Good	X		A
218-Y		<i>Craetagus</i>	Hawthorne	23,16,17,18,12,9,10cm	8 trunk multi poor, many hollow trunkds	Fair		X	D
219-Y		<i>Malus sp.</i>	Apple	28,21,26,24cm	Becomes multi trunk at 1m. Hollow trunks, bark peeled	Poor		X	A
220-Y		<i>Rhamnus cathartica</i>	Buckthorn	21,8,13	Invasive species	Poor		X	B
221-Y		<i>Malus sp.</i>	Apple	23cm	Wound on trunk, healed but deep	Fair	X		A
222-Y		<i>Malus sp.</i>	Apple	32,43cm	large two trunk, peeled bark, conks at base	Good	X		D
223-Y		<i>Malus sp.</i>	Apple	32,34,43cm	Good	Good	X		A
224-Y		<i>Malus sp.</i>	Apple	9,13,6,17,13,14 cm	Multi trunk clump- 6 trunk. Visible insect damage, bark peeled	Fair	X		D

### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.●	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
225-Y		<i>Malus sp.</i>	Apple	40,33,42	3 Trunk, hollows, tisted with cracks	Fair		X	B
226-Y		<i>Prunus?</i>	Cherry	37cm	damage at trunk	Good	X		D
227-Y		<i>Malus sp.</i>	Apple	32cm	damage at trunk	Good	X		A
228-Y		<i>Malus sp.</i>	Apple	33,37cm	2 trunk multi. One trunk dead	Fair		X	A
229-Y		<i>Malus sp.</i>	Apple	20,22	2 trunk multi trunk specimen	Good	X		A
230-Y		<i>Malus sp.</i>	Apple	24,16,17,19 cm	Multi trunk clump 4 trunk	Good	X		A
1	Metal tags	<i>Prunus serotina</i>	Black Cherry	27.5cm	Nice tree	Good	X		A
2		<i>Mystery tree</i>	?	48cm		Good	X		A
3		<i>Acer sp.</i>	Maple	23.5cm	Good	Good	X		A
4		<i>Thuja sp.</i>	Cedar	29.5cm	Good	Good	X		A
5		<i>Thuja sp.</i>	Cedar	32cm	Good	Good	X		A
6		<i>Acer sp.</i>	Maple	46cm	Good	Good	X		A
7		<i>Thuja sp.</i>	Cedar	21cm	Good	Good	X		A
8		<i>Thuja sp.</i>	Cedar	25.5cm, 28.5cm	2 Trunk Multi trunk. Good as a group with trees no. 8-12	Good	X		A
9		<i>Thuja sp.</i>	Cedar	21.5cm	Good as part of a group	Good	X		A



### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.●	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
10		<i>Thuja sp.</i>	Cedar	20.5c22.5,24cm	3 Stem co-dominant trunk. Retain as part of group	Good	X		A
11		<i>Thuja sp.</i>	Cedar	28.5cm	Good as part of a group	Good	X		A
12		<i>Acer saccharum</i>	Sugar Maple	44cm	Good	Good	X		A
13		<i>Thuja sp.</i>	Cedar	31cm	Good	Good	X		A
14		<i>Malus sp.</i>	Apple	26.5cm	Poor but retain as part of group.	Poor	X		A
15		<i>Thuja sp.</i>	Cedar	39cm	Good	Good	X		A
16		<i>Craetagus</i>	Hackberry	20.5cm, 26.5cm	Good	Good	X		A
17		<i>Populus sp.</i>	Poplar	34,30,35	3 trunk multi trunk specimen. 1 Trunk dead	Fair		X	A
18		<i>Thuja sp.</i>	Cedar	33,38cm	Two trunk multi trunk specimen	Good	X		A
19		<i>Thuja sp.</i>	Cedar clump	22,32,32,41	4 trunk multi trunk specimen	Good	X		A
20		<i>Thuja sp.</i>	Cedar clump	45,30cm	Good	Good	X		A
21		<i>Thuja sp.</i>	Cedar clump	50,30,48,20cm	Good	Good	X		A
22		<i>Malus sp.</i>	Apple	42cm	Mostly dead, poor form.	Poor		X	A
23		<i>Acer negundo</i>	Manitoba Maple	20,20,17cm	3 trunk multi trunk specimen.	Good	X		A
24		<i>Acer negundo</i>	Manitoba Maple	34,17cm	2 trunk multi trunk specimen	Good	X		A

### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.●	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
25		<i>Thuja sp.</i>	Cedar	36,40cm	2 trunk multi trunk specimen	Good	X		A
26		<i>Thuja sp.</i>	Cedar	22,14,32,28,15 cm	5 trunk multi trunk specimen	Good	X		A
27		<i>Thuja sp.</i>	Cedar	13,25,25,26,27 cm	6 trunk multi trunk specimen	Good	X		A
28		<i>Thuja sp.</i>	Cedar	25,10,11,10,12, 26,17,7,17,30,9 cm	12 trunk multi trunk clump	Good	X		A
29		<i>Thuja sp.</i>	Cedar	33,35,24,27,20, 25,25 cm	7 trunk multi trunk clump	Good	X		A
30		<i>Picea</i>	Spruce	23cm	Good	Good	X		A
31		<i>Tilia cordata</i>	Linden	27cm	Good	Good	X		A
32		<i>Picea</i>	Spruce	23cm	Good	Good	X		A
33		<i>Picea pungens</i>	Spruce	21.5cm	Pruned out dead wood	Good	X		A
34		<i>Picea pungens</i>	Spruce	21.5cm	Pruned out dead wood	Good	X		A
35		<i>Picea pungens</i>	Spruce	26.5cm	Good	Good	X		A
36		<i>Thuja sp.</i>	Cedar clump	29.5,32,10,11,2 6,9 cm	6 trunk multi trunk specimen	Good	X		A
37		<i>Tilia cordata</i>	Linden	28.5cm,	Becomes co dominant above dbh location. Remove suckers	Good	X		A
38		<i>Malus sp.</i>	Apple	32,28,18,20cm	Multi trunk thicket, poor form	Fair		X	A
39		<i>Acer sp.</i>	Maple sp.	21,23,,23,27,18, 29 cm	Poor form	Poor		X	A

### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.●	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
40		<i>Tilia cordata</i>	Linden	30cm	Limbs poorly removed	Good	X		A
41		<i>Tilia cordata</i>	Linden	38 cm	Good	Good	X		A
42		<i>Tilia cordata</i>	Linden	21.5 cm	Good	Good	X		A
43		<i>Tilia cordata</i>	Linden	71 cm	Co-dominant with a deep split in trunk	Fair		X	A
44		<i>Tilia cordata</i>	Linden	41.5,40cm	2 trunk multi trunk. Some bark loss on lower branches. Retain as part of group with trees no. 43-48.	Good	X		A
45		<i>Tilia cordata</i>	Linden	46cm	Good	Good	X		A
46		<i>Tilia cordata</i>	Linden	42,42cm	Good	Good	X		A
47		<i>Tilia cordata</i>	Linden	47 cm	Co- dominant, Good	Good	X		A
48		<i>Tilia cordata</i>	Linden	42 cm	Good	Good	X		A
49		<i>Tilia americana</i>	Basswood	38,46,43,43,41 cm	Some hollows at base, dead crossing branches. Prune out dead wood	Fair	X		A
50		<i>Tilia americana</i>	Basswood	31,61,53 cm	3 trunk multi trunk specimen	Good	X		A
51		<i>Tilia americana</i>	Basswood	59,46 cm	2 trunk multi trunk specimen.	Good	X		A
52		<i>Picea pungens glauca</i>	Blue Spruce	30cm	Good	Good	X		A
53		<i>Picea pungens glauca</i>	Blue Spruce	32cm	Good	Good	X		A
54		<i>Picea pungens glauca</i>	Blue Spruce	36cm	Good	Good	X		A

### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.●	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
55		<i>Picea pungens glauca</i>	Blue Spruce	27cm	30% Dead	Fair		X	A
56		<i>Pinus sylvestris</i>	Scot's Pine	27.5cm	Good	Good	X		A
57		<i>Fraxinus</i>	Ash	49cm	Fair?	Fair	X		A
58		<i>Fraxinus</i>	Ash	40cm	Many dead branches	Poor		X	A
59		<i>Fraxinus</i>	Ash	33.5cm	Many dead branches	Poor		X	A
60		<i>Mystery Tree</i>	?			Good	X		A
61		<i>Thuja sp.</i>	Eastern White Cedar	9,7,17,26,8,16,2 2,8 cm	8 clump multi trunk specimen	Good	X		A
62		<i>Thuja sp.</i>	Eastern White Cedar	22,11,14,15,11, 17,21,19 cm	8 clump multi trunk specimen	Good	X		A
63		<i>Thuja sp.</i>	Eastern White Cedar	48cm	tree becomes mult trunk above dbh location	Good	X		A
64		<i>Thuja sp.</i>	Eastern White Cedar	26,16,30,31,10, 19 cm	6 trunk multi trunk specimen	Good	X		A
65		<i>Thuja sp.</i>	Eastern White Cedar	44,20,20,28 cn	4 trunk multi trunk specimen	Good	X		A
66		<i>Thuja sp.</i>	Eastern White Cedar	38, 39cm	2 trunk multi trunk specimen.	Good	X		A
67		<i>Thuja sp.</i>	Eastern White Cedar	12,20,8,17,25,1 9,34,10,11 cm	9 trunk multi trunk specimen.	Good	X		A
68		<i>Thuja sp.</i>	Eastern White Cedar	30,23,26,6,21 16,15,7,10 cm	Good	Good	X		A
69		<i>Thuja sp.</i>	Eastern White Cedar	32,28,15,22,33 cm	Good	Good	X		A

### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.*	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
70		<i>Thuja sp.</i>	Eastern White Cedar	5,15,15,19,21,7,24,17,6 cm	8 trunk multi trunk specimen	Good	X		A
71		<i>Thuja sp.</i>	Eastern White Cedar	21,21,8,13,15,24,7,12,19,20,1	11 trunk multi trunk specimen	Good	X		A
72		<i>Thuja sp.</i>	Eastern White Cedar	37,35 cm	2 trunk multi trunk specimen.	Good	X		A
73		<i>Thuja sp.</i>	Eastern White Cedar	14,27,9,23,22,20,8,12,21 cm	9 trunk multi trunk specimen.	Good	X		A
74		<i>Thuja sp.</i>	Eastern White Cedar	28,21,31,22,16,24,26 cm	7 trunk multi trunk specimen	Good	X		A
75		<i>Thuja sp.</i>	Eastern White Cedar	19.5,16,14,33,21,20,20 cm	7 trunk multi trunk specimen	Good	X		A
76		<i>Thuja sp.</i>	Eastern White Cedar	33,34 cm	2 trunk multi trunk specimen.	Good	X		A
77		<i>Thuja sp.</i>	Eastern White Cedar	17,19,22,23,22 cm	5 trunk multi trunk specimen	Good	X		A
78		<i>Pinus sylvestris</i>	Scot's Pine	28 cm	Dead tree	Poor		X	A
79		<i>Pinus sylvestris</i>	Scot's Pine	28.5 cm	Good	Good	X		A
80		<i>Picea pungens</i>	Spruce	31 cm	Good	Good	X		A
81		<i>Populus sp.</i>	Poplar species	53,55cm	Good	Good	X		A
82		<i>Picea pungens</i>	Spruce	33 cm	Good	Good	X		A
83		<i>Pinus sylvestris</i>	Scot's Pine	25 cm	50% dead. Prune if maintaining	Fair		X	A
84		<i>Populus sp.</i>	Poplar species	78cm	Becomes co-dominant, included bark	Good	X		A

### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.●	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
85		<i>Acer platanoides</i>	Norway Maple	39 cm	Good	Good	X		A
86		<i>Pinus sylvestris</i>	Scot's Pine	31 cm	Good	Good	X		A
87		<i>Picea pungens</i>	Spruce	21.5 cm	Good	Good	X		A
88		<i>Pinus sylvestris</i>	Scot's Pine	33.5 cm	Good	Good	X		A
89		<i>Picea pungens</i>	Spruce	27.5 cm	Good	Good	X		A
90		<i>Picea pungens</i>	Spruce	30.5 cm	Good	Good	X		A
91		<i>Pinus sylvestris</i>	Scot's Pine	38 cm	Good	Good	X		A
92		<i>Picea pungens glauca</i>	Blue Spruce	34.5 cm	Good	Good	X		A
93		<i>Pinus sylvestris</i>	Scot's Pine	34 cm	Good	Good	X		A
94		<i>Picea pungens</i>	Spruce	40 cm	Good	Good	X		A
95		<i>Picea pungens glauca</i>	Spruce	28 cm	Good	Good	X		A
96		<i>Picea pungens glauca</i>	Spruce	33 cm	Good	Good	X		A
97		<i>Pinus sylvestris</i>	Scot's Pine	37 cm	Good	Good	X		A
98		<i>Pinus sylvestris</i>	Scot's Pine	27 cm	no needles, dead	Poor		X	A
99		<i>Pinus sylvestris</i>	Scot's Pine	27.5 cm	low number of needles	Fair		X	A

### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.●	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
100		<i>Acer saccharum</i>	Sugar Maple	53 cm	Good	Good	X		A
101		<i>Pinus sylvestris</i>	Scot's Pine	35.5 cm	Good	Good	X		D
102		<i>Pinus sylvestris</i>	Scot's Pine	36.5 cm	Good	Good	X		D
103		<i>Pinus sylvestris</i>	Scot's Pine	28 cm	Good	Good	X		D
104		<i>Pinus sylvestris</i>	Scot's Pine	38 cm	Good	Good	X		D
105		<i>Pinus sylvestris</i>	Scot's Pine	41.5 cm	Good- becomes co-dominant	Good	X		D
106		<i>Larix decidua</i>	Larch	26.5 cm	Good	Good	X		A
107		<i>Larix decidua</i>	Larch	28 cm	Good	Good	X		A
108		<i>Pinus sylvestris</i>	Scot's Pine	32 cm	Good	Good	X		D
109		<i>Picea pungens</i>	Spruce	28 cm	Good	Good	X		D
110		<i>Larix decidua</i>	Larch	25 cm	Good	Good	X		D
111		<i>Larix decidua</i>	Larch	25.5 cm	Good	Good	X		A
112		<i>Larix decidua</i>	Larch	29 cm	Good	Good	X		D
113		<i>Larix decidua</i>	Larch	25 cm	Good	Good	X		A
114		<i>Picea pungens glauca</i>	Blue Spruce	31.5 cm	Good	Good	X		D

### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.●	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
115		<i>Picea pungens glauca</i>	Blue Spruce	32 cm	Good	Good	X		A
116		<i>Pinus sylvestris</i>	Scot's Pine	34 cm	Good	Good	X		D
117		<i>Malus sp.</i>	Apple sp.	32,37 cm	2 trunk multi trunk specimen	Good	X		D
118		<i>Pinus sylvestris</i>	Scot's Pine	34.5 cm	Good	Good	X		D
119		<i>Picea pungens</i>	Spruce	29 cm	Good	Good	X		D
120		<i>Picea pungens glauca</i>	Blue Spruce	27 cm	50% branches poor	Good-Fair	X		D
121		<i>Picea pungens</i>	Spruce	27 cm	Good	Good	X		D
122		<i>Picea pungens glauca</i>	Blue Spruce	22 cm	Good	Good	X		D
123		<i>Tilia cordata</i>	Linden	26 cm	Good	Good	X		A
124		<i>Picea pungens</i>	Spruce	24 cm	Good- Retain as part of group.	Good	X		D
125		<i>Acer platanoides</i>	Norway Maple	35.5 cm	Good- Retain as part of group.	Good	X		D
	Note 3 trees not tagged	<i>Picea sp.</i>	Spruces	3 trees <20cm	Good	Good	X		D
126		<i>Picea pungens</i>	Spruce	22 cm	Good	Good	X		D
127		<i>Acer platanoides</i>	Norway Maple	18,23 cm	Becomes co dominant at 1m ht. Central leader strangled by tree staking wire.	Good	X		D
128		<i>Picea pungens glauca</i>	Blue Spruce	23 cm	Good	Good	X		D
129		<i>Picea abies</i>	Norway Spruce	19.5 cm	Good - retain as part of group. Trees no. 129-138	Good	X		D



### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.●	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
130		<i>Picea pungens glauca</i>	Blue Spruce	27 cm	Good- retain as part of group. Trees no. 129-138	Good	X		D
131		<i>Picea pungens</i>	Spruce	26.5 cm	Good- retain as part of group. Trees no. 129-138	Good	X		D
132		<i>Picea abies</i>	Spruce	23 cm	Good- retain as part of group. Trees no. 129-138	Good	X		D
133		<i>Quercus robur</i>	English Oak	27 cm	Good- retain as part of group. Trees no. 129-138	Good	X		A
134		<i>Picea pungens glauca</i>	Blue Spruce	25 cm	Good- retain as part of group. Trees no. 129-138	Good	X		D
135		<i>Picea pungens glauca</i>	Blue Spruce	22 cm	Good- retain as part of group. Trees no. 129-138	Good	X		D
136		<i>Picea pungens glauca</i>	Blue Spruce	25 cm	Good- retain as part of group. Trees no. 129-138	Good	X		D
137		<i>Picea abies</i>	Spruce	22 cm	Good- retain as part of group. Trees no. 129-138	Good	X		D
138		<i>Acer platanoides</i>	Norway Maple	23.5,30 cm	Good	Good	X		D
139		<i>Picea abies</i>	Spruce	26 cm	Good	Good	X		D
140		<i>Picea abies</i>	Norway Spruce	24 cm	Good	Good	X		D
141		<i>Picea abies</i>	Norway Spruce	24 cm	Good	Good	X		A
142		<i>Picea abies</i>	Norway Spruce	22 cm	Good	Good	X		D
143		<i>Mystery Tree</i>	?	22,14,12 cm	Tree at fenceline. Dead	Poor		X	B
144		<i>Picea abies</i>	Norway Spruce	22 cm	Good	Good	X		A
145		<i>Picea abies</i>	Norway Spruce	24 cm	Good	Good	X		D

### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.•	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
146		<i>Picea abies</i>	Norway Spruce	23.5 cm	Good	Good	X		A
147		<i>Picea abies</i>	Norway Spruce	23 cm	Good	Good	X		D
148		<i>Picea abies</i>	Norway Spruce	24 cm	Good	Good	X		D
149		<i>Picea abies</i>	Norway Spruce	22 cm	Good	Good	X		D
150		<i>Picea abies</i>	Norway Spruce	23 cm	Good	Good	X		D
151		<i>Picea abies</i>	Norway Spruce	29 cm	Good	Good	X		D
152		<i>Picea abies</i>	Norway Spruce	26 cm	Good	Good	X		D
153		<i>Picea abies</i>	Norway Spruce	30 cm	Good	Good	X		D
154		<i>Picea abies</i>	Norway Spruce	28 cm	Good	Good	X		D
155		<i>Picea abies</i>	Norway Spruce	26 cm	Good	Good	X		D
156		<i>Tilia americana</i>	Basswood	38 cm	Large branch scars, awkward branch habit	Good	X		A
157		<i>Tilia americana</i>	Basswood	36,27 cm	Good	Good	X		A
158		<i>Tilia americana</i>	Basswood	34, 54 cm	Good	Good	X		A
159		<i>Tilia americana</i>	Basswood	39, 39 cm	Upper part of tree is bent over significantly, suckering at base- retain as part of group	Good	X		A
160		<i>Tilia americana</i>	Basswood	47, 57 cm	2 trunk specimen- larger trunk dead	Fair		X	A
161		<i>Tilia americana</i>	Basswood	30.5, 29.5 cm	2 trunk specimen-shorter trunk broken off approx. 2.5m. Tall trunk poor	Fair		X	A

### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.●	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
162		<i>Ostrya virginiana</i>	Hop-hornbeam	21 cm	Good- retain as part of group with trees below	Good	X		A
	trees not surveyed	<i>Ostrya virginiana</i>	Hop-hornbeam	<20 cm	2 trees < 20cm dbh. Retain as part of group with T-163 above.	Good	X		A
163		<i>Malus sp.</i>	Apple	24 cm	Good	Good	X		A
164		<i>Malus sp.</i>	Apple	18,24,15 cm	3 trunk multi trunk specimen	Good	X		A
165		<i>Picea abies</i>	Norway Spruce	26 cm	Good	Good	X		A
166		<i>Tilia americana</i>	Basswood	46 cm	Canopy poorly branched, suckering at base	Fair	X		A
167		<i>Acer saccharum</i>	Silver Maple	76 cm	Good	Good	X		A
168		<i>Tilia americana</i>	Basswood	43,33,22,37 cm	4 trees growing close together.	Good	X		A
169		<i>Ostrya virginiana</i>	Hop-hornbeam	45 cm	Good	Good	X		A
170		<i>Picea abies</i>	Norway Spruce	20.5 cm	Good	Good	X		A
171		<i>Picea abies</i>	Norway Spruce	19.5 cm	Good	Good	X		A
172		<i>Picea abies</i>	Norway Spruce	19.5 cm	Good	Good	X		A
173		<i>Acer saccharum</i>	Sugar Maple	62 cm	Good	Good	X		A
174		<i>Tilia americana</i>	Basswood	50, 29.5 cm	Good	Good	X		A
175		<i>Fraxinus</i>	Ash	47 cm	Fair	Fair		X	A
176		<i>Ostrya virginiana</i>	Hop-hornbeam	39 cm	Good	Good	X		A
177		<i>Tilia americana</i>	Basswood	55 cm	Good	Good	X		A

### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.•	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
178		<i>Tilia americana</i>	Basswood	55 cm	Good	Good	X		A
179		<i>Picea abies</i>	Spruce	21.5 cm	Good- retain as a group with trees 179-182	Good	X		A
180		<i>Picea abies</i>	Spruce	22 cm	Good- retain as a group with trees 179-182	Good	X		A
181		<i>Picea abies</i>	Norway Spruce	22.5 cm	Good- retain as a group with trees 179-182	Good	X		A
182		<i>Picea abies</i>	Spruce	21 cm	Good- retain as a group with trees 179-182	Good	X		A
183		<i>Tilia americana</i>	Basswood	40 cm	Good	Good	X		A
184		<i>Tilia americana</i>	Basswood	62,53,32 cm	52 cm trunk broken off at approx. 3m ht.	Good	X		A
185		<i>Picea</i>	Spruce	24 cm	Good-retain as a group with trees 185-190	Good	X		A
	2 trees not surveyed	<i>Picea</i>	Spruce		2 less than 20 cm- retain as a group with trees 185-190	Good	X		RELOCATE
186		<i>Picea abies</i>	Norway Spruce	25.5	Good- retain as a group with trees 185-190	Good	X		A
187		<i>Picea abies</i>	Norway Spruce	28 cm	Good- retain as a group with trees 185-190	Good	X		A
188		<i>Picea abies</i>	Norway Spruce	21.5 cm	Good- retain as a group with trees 185-190	Good	X		A
189		<i>Picea abies</i>	Norway Spruce	27.5 cm	Good- retain as a group with trees 185-190	Good	X		A
	3 trees not surveyed	<i>Picea</i>	Spruce		3 less than 20 cm- retain as a group with trees 185-190	Good	X		RELOCATE
190		<i>Larix decidua</i>	Larch	27 cm	Good- retain as a group with trees 185-190	Good	X		A
191		<i>Tilia americana</i>	Basswood	47 cm	Good	Good	X		A

### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.•	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
	2 trees not measured	<i>Picea, Larix</i>	Spruce, Larch	<20 cm	2 less than 20 cm- retain as a group with trees 185-190	Good	X		A
192		<i>Picea abies</i>	Spruce	21 cm	Good	Good	X		A
193		<i>Picea abies</i>	Spruce	25.5 cm	Good	Good	X		A
194		<i>Picea abies</i>	Spruce	21 cm	Good	Good	X		A
195		<i>Larix decidua</i>	Larch	26.5 cm	Good	Good	X		A
196		<i>Larix decidua</i>	Larch	24 cm	Good	Good	X		A
197		<i>Picea pungens glauca</i>	Blue Spruce	22 cm	Good	Good	X		A
	1 tree not surveyed	<i>Picea</i>	Spruce		1 less than 20 cm	Good	X		A
198		<i>Larix decidua</i>	Larch	24 cm	Good	Good	X		A
199		<i>Malus</i>	Apple	22,20,18 cm	Good, a fourth trunk is broken below dbh height.	Good	X		A
200		<i>Picea pungens glauca</i>	Blue Spruce	28 cm	Good	Good	X		A
	2 trees not surveyed	<i>Picea</i>	Spruce		2 less than 20 cm	Good	X		RELOCATE
201		<i>Tilia americana</i>	Basswood	63 cm	Good	Good	X		A
	1 tree not surveyed	<i>Picea</i>	Spruce		1 less than 20 cm	Good	X		RELOCATE
202		<i>Picea abies</i>	Spruce	22 cm	Good	Good	X		A
203		<i>Tilia americana</i>	Basswood	48, 38 cm	2 trunk multi trunk specimen	Good	X		A

### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.●	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
204		<i>Acer saccharum</i>	Sugar Maple	42.5 cm	Good	Good	X		A
205		<i>Fraxinus sp.</i>	Ash	38 cm	Evidence of borer damage- trunk of adjacent ash tree cut down	Poor		X	A
206		<i>Fraxinus sp.</i>	Ash	41 cm	Evidence of borer damage (All ash trees in group)	Poor		X	A
	3 trees not surveyed	<i>Acer sp.</i>	Maple		3 less than 20 cm	Good	X		D
207		<i>Picea pungens glauca</i>	Blue Spruce	27 cm	Good	Good	X		D
208		<i>Picea abies</i>	Spruce	29 cm	Good	Good	X		D
209		<i>Picea abies</i>	Spruce	29 cm	Good	Good	X		D
210		<i>Picea abies</i>	Spruce	30 cm	Good	Good	X		D
211		<i>Malus sp.</i>	Apple	30, 40 cm	1 hollow trunk - suckering at base. Very dense	Fair		X	D
212		<i>Malus</i>	Apple	33 cm	Good	Good	X		D
213		<i>Malus sp.</i>	Apple	48 cm	Large crack in trunk, hollow half way up	Fair		X	D
214		<i>Picea pungens glauca</i>	Blue Spruce	30 cm	Good	Good	X		D
215		<i>Rhamnus cathartica</i>	Buckthorn	31,21,12,18,18,14,9 cm	Buckthorn thicket, Invasive	Fair		X	B
216		<i>Picea pungens glauca</i>	Blue Spruce	30 cm	Good	Good	X		D
217		<i>Picea pungens glauca</i>	Blue Spruce	34.5 cm	Good	Good	X		D
218		<i>Malus sp.</i>	Apple	28.5 cm	Good	Good	X		D

### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.*	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
219		<i>Malus sp.</i>	Apple	22, 27 cm	Good	Good	X		D
220		<i>Pinus nigra</i>	Austrian Pine	38 cm	No needles, Dead	Poor		X	B
221		<i>Pinus nigra</i>	Austrian Pine	36 cm	Good	Good	X		D
222		<i>Picea pungens glauca</i>	Blue Spruce	31 cm	Good	Good	X		D
223		<i>Malus sp.</i>	Apple	29, 25, 29 cm	Bark removed 2 trunks in good condition	Fair	X		D
224		<i>Picea pungens glauca</i>	Blue Spruce	30 cm	Good	Good	X		D
225		<i>Picea pungens glauca</i>	Blue Spruce	31 cm	Good	Good	X		D
226		<i>Picea pungens glauca</i>	Blue Spruce	31 cm	Good	Good	X		D
227		<i>Tilia cordata</i>	Linden	40 cm	Evidence of root girdling	Good	X		D
228		<i>Fraxinus</i>	Ash	49.5 cm	Poor, dead branches	Poor		X	B
229		<i>Prunus serotina</i>	Black Cherry	41 cm	Good	Good	X		D
230		<i>Acer saccharum</i>	Sugar Maple	55.5 cm, 31 cm	Low branching multi trunk specimen	Good	X		D
231		<i>Pinus nigra</i>	Austrian Pine	30, 35, 41 cm	Low branching multi trunk specimen	Good	X		D
232		<i>Pinus nigra</i>	Austrian Pine	29 cm	Good- retain as part of group	Good	X		A
233		<i>Pinus strobus</i>	Eastern White Pine	27 cm	Good- retain as part of group	Good	X		A
234		<i>Pinus strobus</i>	Eastern White Pine	25 cm	Good- retain as part of group	Good	X		A

### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.•	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
235		<i>Pinus strobus</i>	Eastern White Pine	27.5 cm	Good- retain as part of group	Good	X		A
236		<i>Pinus strobus</i>	Eastern White Pine	32 cm	Good- retain as part of group	Good	X		A
237		<i>Pinus strobus</i>	Eastern White Pine	38.5 cm	Good- retain as part of group	Good	X		A
238		<i>Pinus strobus</i>	Eastern White Pine	31.5 cm	Good- retain as part of group	Good	X		A
239		<i>Pinus strobus</i>	Eastern White Pine	28 cm	Dead	Poor		X	A
240		<i>Pinus strobus</i>	Eastern White Pine	24 cm	Good	Good	X		A
241		<i>Pinus strobus</i>	Eastern White Pine	36.5 cm	Good	Good	X		A
242		<i>Pinus strobus</i>	Eastern White Pine	31.5 cm	Good	Good	X		A
243		<i>Pinus nigra</i>	Austrian Pine	22 cm	Good	Good	X		A
244		<i>Pinus nigra</i>	Austrian Pine	23 cm	Dead- no needles	Poor		X	A
245		<i>Pinus nigra</i>	Austrian Pine	22.5 cm	Good	Good	X		A
	1 tree not surveyed	<i>Pinus nigra</i>	Austrian Pine	<20cm	Good	Good	X		A
246		<i>Thuja occidentalis</i>	Eastern Cedar	30.5 cm	Good	Good	X		A
247		<i>Pinus sylvestris</i>	Scot's Pine	31.5 cm	Good	Good	X		A
248		<i>Pinus nigra</i>	Austrian Pine	30 cm	>30% dead branches	Fair		X	A
249		<i>Pinus sylvestris</i>	Scot's Pine	27.5 cm	>60% dead	Poor		X	A



### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.●	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
250		<i>Picea glauca</i>	Spruce	20 cm	Good- retain as part of group with trees 250-253	Good	X		A
251		<i>Picea glauca</i>	Spruce	24 cm	Good- retain as part of group with trees 250-253	Good	X		A
252		<i>Picea glauca</i>	Spruce	26 cm	Good- retain as part of group with trees 250-253	Good	X		A
253		<i>Pinus sylvestris</i>	Scot's Pine	47.5 cm	Good- retain as part of group with trees 250-253	Good	X		A
254		<i>Pinus nigra</i>	Austrian Pine	25 cm	Good- retain as part of group with trees 254-259	Good	X		A
255		? <i>Pinus nigra</i>	Austrian Pine	27 cm	Many dead branches- retain as group	Fair		X	A
256		<i>Pinus nigra</i>	Austrian Pine	20 cm	>70% dead wood- retain as group	Poor		X	A
257		<i>Pinus nigra</i>	Austrian Pine	30 cm	Good- retain as part of group with trees 254-259	Good	X		A
258		<i>Pinus nigra</i>	Austrian Pine	26.5 cm	Good- retain as part of group with trees 254-259	Good	X		A
259		<i>Pinus nigra</i>	Austrian Pine	24.5 cm	Good- retain as part of group with trees 254-259	Good	X		A
260		<i>Pinus nigra</i>	Austrian Pine	20 cm	Fair- poorly branched	Fair		X	A
261		<i>Picea abies</i>	Spruce	23 cm	Good- retain as part of group- with trees 261-264	Good	X		A
262		<i>Picea abies</i>	Spruce	21 cm	Good- retain as part of group- with trees 261-264	Good	X		A
263		<i>Picea abies</i>	Spruce	25 cm	Good- retain as part of group- with trees 261-264	Good	X		A
264		<i>Picea abies</i>	Spruce	24 cm	Good- retain as part of group- with trees 261-264	Good	X		A
265		<i>Pinus nigra</i>	Austrian Pine	30 cm	50% dead- Fair	Fair		X	A

### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.●	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
266		<i>Pinus nigra</i>	Austrian Pine	29 cm	Good	Good	X		A
267		<i>Pinus strobus</i>	Eastern White Pine	50 cm	Good	Good	X		A
268		<i>Thuja occidentalis</i>	Eastern Cedar	19,19,18,19,20,12,14,20	Multi trunk specimen- overgrown with Buckthorn	Good	X		A
269		<i>Thuja occidentalis</i>	Eastern Cedar	45 cm	Good	Good	X		A
270		<i>Pinus strobus</i>	Eastern White Pine	41.5 cm	Good	Good	X		A
271		<i>Pinus strobus</i>	Eastern White Pine	44.5 cm	Good	Good	X		A
272		<i>Picea abies</i>	Spruce	20 cm	Good	Good	X		A
273		<i>Picea abies</i>	Spruce	29 cm	Good	Good	X		A
274		<i>Pinus nigra</i>	Austrian Pine	26 cm	Good	Good	X		A
275		<i>Picea abies</i>	Spruce	29 cm	Good	Good	X		A
276		<i>Picea abies</i>	Spruce	34 cm	Good	Good	X		A
277		<i>Picea abies</i>	Spruce	26 cm	Good	Good	X		A
278		<i>Picea abies</i>	Spruce	24 cm	Sparsely branched - retain as part of group	Fair	X		A
279		<i>Acer platanoides</i>	Norway Maple	26,32,28,41 cm	Low branch 4 trunk multi trunk. Included bark	Good	X		A
280		<i>Thuja occidentalis</i>	Eastern Cedar	44.5 cm	Good	Good	X		A
281		<i>Thuja occidentalis</i>	Eastern Cedar	9,14,17,26,22 cm	5 trunk multi trunk specimen	Good	X		A

### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.●	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
282		<i>Thuja occidentalis</i>	Eastern Cedar	14,16,24 cm	3 trunk multi trunk specimen	Good	X		A
283		<i>Malus sp.</i>	Apple	22.5 cm	Good	Good	X		A
284		<i>Thuja occidentalis</i>	Eastern Cedar	24,24.5,14,11,6 cm	5 trunk multi trunk specimen	Good	X		A
285		<i>Pinus nigra</i>	Austrian Pine	45 cm	Good	Good	X		A
286		<i>Tilia</i>	Linden	29,18,22,32,29,27 cm	6 trunk multi trunk specimen	Good	X		A
287		<i>Pinus nigra</i>	Austrian Pine	40.5 cm	Good	Good	X		A
288		<i>Pinus sylvestris</i>	Scot's Pine	39.5 cm	Good	Good	X		A
289		<i>Thuja occidentalis</i>	Eastern Cedar	19,18,14,11,16,9 cm	6 trunk multi trunk specimen. Buckthorn infested. Remove Buckthorn	Fair	X		A
290		<i>Thuja occidentalis</i>	Eastern Cedar	22,19,17,16,11 cm	5 trunk multi trunk specimen. Buckthorn infested. Remove Buckthorn	Fair	X		A
291		<i>Thuja occidentalis</i>	Eastern Cedar	22,16,17,11,18 cm	5 Trunk multi trunk specimen.	Good	X		A
292		<i>Rhamnus cathartica</i>	Common Buckthorn	4,8,17,17,21,9,7,1	Invasive Species	Fair		X	A
293		<i>Thuja occidentalis</i>	Eastern Cedar	41 cm	Good	Good	X		A
294		<i>Thuja occidentalis</i>	Eastern Cedar	24, 28,29,17 cm	Good	Good	X		A
295		<i>Pinus nigra</i>	Austrian Pine	31 cm	Good	Good	X		D
296		<i>Pinus strobus</i>	Eastern White Pine	46 cm	Good- retain as part of group	Good	X		D
297		<i>Tsuga canadensis</i>	Eastern Hemlock	25 cm	Good- retain as part of group	Good	X		D

### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.*	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
298		<i>Pinus strobus</i>	Eastern White Pine	27 cm	Good- retain as part of group	Good	X		D
299		<i>Pinus strobus</i>	Eastern White Pine	38 cm	Good- retain as part of group	Good	X		D
300		<i>Thuja occidentalis</i>	Eastern Cedar	6,5,10,14,19,19	6 trunk multi trunk specimen	Good	X		D
301		<i>Thuja occidentalis</i>	Eastern Cedar	29 cm	Good	Good	X		D
302		<i>Pinus strobus</i>	Eastern White Pine	33 cm	Good	Good	X		D
303		<i>Pinus strobus</i>	Eastern White Pine	43 cm	Good	Good	X		A
304		<i>Pinus strobus</i>	Eastern White Pine	39 cm	Good	Good	X		A
305		<i>Pinus strobus</i>	Eastern White Pine	40 cm	Good	Good	X		A
306		<i>Pinus strobus</i>	Eastern White Pine	50 cm	Good	Good	X		A
307		<i>Pinus strobus</i>	Eastern White Pine	40 cm	Good	Good	X		A
308		<i>Pinus strobus</i>	Eastern White Pine	58.5 cm	Good	Good	X		A
309		<i>Pinus strobus</i>	Eastern White Pine	49.5 cm	Good	Good	X		A
310		<i>Malus sp.</i>	Apple	20,26,20.5 cm	3 trunk multi trunk specimen	Good	X		D
311		<i>Pinus sylvestris</i>	Scot's Pine	75 cm	Good becomes co dominant above dbh location	Good	X		A
312		<i>Thuja occidentalis</i>	Eastern Cedar	19,22.5, 23,20,17 cm	Good	Good	X		A
313		<i>Thuja occidentalis</i>	Eastern Cedar	38,28,35,22,18, 37 cm	6 trunk multi trunk specimen	Good	X		A

### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.*	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
314		<i>Malus sp.</i>	Apple	26, 48 cm	Trunks twisted together	Good	X		D
315		<i>Pinus sylvestris</i>	Scot's Pine	51 cm	Leader cut. Becomes co-dominant around 80 cm ht. Trunks too close to determine	Good	X		D
316		<i>Ulmus sp.</i>	Elm	25 cm	Good	Good	X		D
317		<i>Picea sp.</i>	Spruce	26 cm	Good	Good	X		A
318		<i>Prunus sp.</i>	Cherry	17,19,18,11,14 cm	5 trunk multi trunk specimen low branching	Good	X		A
319		<i>Larix decidua</i>	Larch	24.5 cm	Good	Good	X		A
320		<i>Rhamnus cathartica</i>	Common Buckthorn	17,15,13,24,18,17,30,9 cm	8 trunk multi trunk specimen- invasive species	Good		X	A
321		<i>Thuja occidentalis</i>	Eastern Cedar	48 cm	Good	Good	X		A
322		<i>Pinus sylvestris</i>	Scot's Pine	35.5 cm	Good	Good	X		A
323		<i>Thuja occidentalis</i>	Eastern Cedar	22,22,24,16 cm	4 trunk multi trunk specimen- infested with buckthorn	Good	X		A
324		<i>Thuja occidentalis</i>	Eastern Cedar	29,26,12,23,20,18 cm	6 trunk multi trunk specimen- infested with buckthorn	Good	X		A
325		<i>Thuja occidentalis</i>	Eastern Cedar	22,18,25 cm	3 trunk multi trunk specimen- infested with buckthorn	Good	X		A
326		<i>Thuja occidentalis</i>	Eastern Cedar	23,13 cm	50% brown- infested with buckthorn	Fair		X	A
327		<i>Acer platanoides</i>	Norway Maple	42 cm	included bark, becomes co dominant at 1.4m dbh.	Good	X		A
328		<i>Thuja occidentalis</i>	Eastern Cedar	21,18,20.5,14,19,8 cm	6 trunk multi trunk specimen- infested with buckthorn	Good	X		A
329		<i>Fraxinus</i>	Ash	28,32,39 cm	Dead	Poor		X	A

### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.●	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
330		<i>Thuja occidentalis</i>	Eastern Cedar	20.5 cm	Good	Good	X		A
331		<i>Thuja occidentalis</i>	Eastern Cedar	22, 9 cm	2 trunk multi trunk specimen	Good	X		A
332		<i>Pinus sylvestris</i>	Scot's Pine	41 cm	Good	Good	X		A
333		<i>Thuja occidentalis</i>	Eastern Cedar	20.5 cm, 7 cm	2 trunk multi trunk specimen	Good	X		A
	2 trees not inventoried	<i>Thuja occidentalis</i>	Eastern Cedar	<20 cm	Good	Good	X		A
334		<i>Thuja occidentalis</i>	Eastern Cedar	21.5 cm, 24 cm	Good	Good	X		A
335		<i>Pinus sylvestris</i>	Scot's Pine	39.5 cm	No leader but good condition	Good	X		A
	5 trees not inventoried	<i>Acer sp.</i>	Maple Sp.	<20cm	2 Saccharum, 3 platanoides	Good	X		D
336		<i>Populus sp.</i>	Lg. Poplar	52,78,45	Multi trunk specimen	Good	X		D
	10 trees not inventoried	<i>various</i>	<i>various</i>	<20 cm	7 Acer sp., 1 Abies concolor, 1 Aesculus , 1 fir	Good	X		D
337		<i>Malus sp.</i>	Apple	86 cm	Many crossing branches, hollow center. Dbh is many trunks now grown together	Fair		X	D
338		<i>Malus sp.</i>	Apple	60 cm	Good- tree leaning	Good	X		A
339		<i>Acer platanoides</i>	Norway Maple	38, 27, 5 cm	3 trunk multi trunk specimen	Good	X		A
340		<i>Thuja occidentalis</i>	Eastern Cedar	7,13,15,22,19, 16,11,8 cm	9 trunk multi trunk specimen	Good	X		D
341		<i>Thuja occidentalis</i>	Eastern Cedar	16,16,9,14 cm	4 trunk multi trunk specimen	Good	X		D
342		<i>Thuja occidentalis</i>	Eastern Cedar	19,18,23 cm	3 trunk multi trunk specimen	Good	X		D

### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.●	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
343		<i>Acer platanoides</i>	Norway Maple	22 cm	Good	Good	X		D
344		<i>Thuja occidentalis</i>	Eastern Cedar	44, 14, 28 cm	Good	Good	X		D
345		<i>Thuja occidentalis</i>	Eastern Cedar	13,15,25,17,32 cm	5 trunk multi trunk specimen- infested with buckthorn	Good	X		D
346		<i>Thuja occidentalis</i>	Eastern Cedar	30,30,35,28 cm	5 trunk multi trunk specimen- infested with buckthorn	Good	X		D
	1 trees not inventoried	<i>Acer platanoides</i>	Norway Maple	<20 cm	8, 19 cm multi trunk specimen	Good	X		D
347		<i>Thuja occidentalis</i>	Eastern Cedar	40,38 cm	Good	Good	X		D
348		<i>Picea abies</i>	Spruce	59 cm	Good	Good	X		D
349		<i>Tilia americana</i>	Basswood	46 cm	Good	Good	X		D
350		<i>Acer negundo</i>	Manitoba Maple	22.5 cm	Good	Good	X		A
351		<i>Thuja occidentalis</i>	Eastern Cedar	40,16,15 cm	3 trunk multi trunk specimen- infested with Manitoba Maple	Good	X		A
352		<i>Thuja occidentalis</i>	Eastern Cedar	3,16,15,24,12 cm	5 trunk multi trunk specimen- infested with Manitoba Maple	Good	X		A
353		<i>Picea sp.</i>	Spruce	52 cm	Good	Good	X		A
354		<i>Thuja occidentalis</i>	Eastern Cedar	21,17 cm	2 trunk multi trunk specimen- infested with buckthorn	Good	X		A
355		<i>Populus sp.</i>	Poplar	100 cm	Good	Good	X		A
356		<i>Betula sp.</i>	Birch	28,29 cm	2 trunk multi trunk specimen	Good	X		A
357		<i>Pinus sylvestris</i>	Scot's Pine	30.5 cm	Good	Good	X		A

### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.●	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
358		<i>Populus sp.</i>	Poplar	90 cm	Good	Good	X		A
359		<i>Acer saccharinum</i>	Silver Maple	63.5 cm	Good	Good	X		A
360		<i>Ulmus</i>	Elm	42 cm	Most bark removed from trunk, not healthy	Poor		X	A
361		<i>Gleditsia triacanthos</i>	Honeylocust	40 cm	Good	Good	X		A
362		<i>Picea abies</i>	Spruce	25 cm	Tree in good condition, although leader is gone	Good	X		A
363		<i>Thuja occidentalis</i>	Eastern Cedar	24,32,26,19 cm	4 trunk multi trunk specimen	Good	X		A
364		<i>Populus sp.</i>	Poplar	45,54 cm	low branch 2 trunk specimen	Good	X		A
365		<i>Populus sp.</i>	Poplar	63,63 cm	trunk splits at 1m high 2 trunk multi trunk. Some bark removed	Good	X		A
366		<i>Thuja occidentalis</i>	Eastern Cedar	29,27,19.5,20, 12 cm	5 trunk multi trunk specimen- infested with buckthorn	Good	X		A
367		<i>Populus sp.</i>	Poplar	44,40.5 cm	2 trunk multi trunk specimen	Good	X		A
368		<i>Thuja occidentalis</i>	Eastern Cedar	32 cm	Good	Good	X		A
369		<i>Thuja occidentalis</i>	Eastern Cedar	35, 27 cm	Good	Good	X		A
370		<i>Populus sp.</i>	Poplar	36,42,43,35 cm	4 trunk multi trunk specimen- 1 trunk dead	Fair	X		A
371		<i>Populus sp.</i>	Poplar	108 cm	Good	Good	X		A
372		<i>Malus sp.</i>	Apple	27 cm	Good	Good	X		A
373		<i>Pinus sylvestris</i>	Scot's Pine	31.5 cm	Good	Good	X		A



### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.●	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
374		<i>Acer sp.</i>	Maple	53 cm	very few buds on tree	Fair	X		D
375		<i>Pinus sylvestris</i>	Scot's Pine	31.5 cm	Good	Good	X		D
376		<i>Acer platanoides</i>	Norway Maple	94 cm	large wound. Center is hollow	Fair		X	D
377		<i>Acer platanoides</i>	Norway Maple	67.5 cm	Good	Good	X		D
378		<i>Malus sp.</i>	Apple	27 cm	Good	Good	X		D
379		<i>Juglans nigra</i>	Black Walnut	44 cm	Good	Good	X		D
380		<i>Acer platanoides</i>	Norway Maple	27, 35 cm	2 trunk multi trunk specimen- 1 trunk hollow	Fair		X	D
381		<i>Picea pungens glauca</i>	Blue Spruce	63,63 cm	trunk splits at 1m high 2 trunk multi trunk. Some bark removed	Good	X		D
382		<i>Robinia pseudoacacia</i>	Black Locust	92 cm	Good	Good	X		D
383		<i>Robinia pseudoacacia</i>	Black Locust	88 cm	Deep split in crotch. Upright form	Fair	X		D
384		<i>Prunus sp.</i>	Cherry sp.	22,23,36 cm	Remove dead branches	Good	X		D
385		<i>Betula sp.</i>	Birch	35,28 cm	2 trunk multi trunk specimen	Good	X		A
386		<i>Robinia pseudoacacia</i>	Black Locust	11,45,35,41 cm	4 trunk multi trunk specimen- crotch at 1m.	Good	X		A
387		<i>Robinia pseudoacacia</i>	Black Locust	27 cm	Good	Good	X		A
388		<i>Fraxinus sp.</i>	Ash	51 cm	Poor- many dead branches	Poor		X	A
389		<i>Acer saccharinum</i>	Silver Maple	44 cm	Good	Good	X		D

### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.♦	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
390		<i>Tilia cordata</i>	Linden	54 cm	Good	Good	X		D
391		<i>Acer platanoides</i>	Norway Maple	60 cm	Good	Good	X		A
392		<i>Acer platanoides</i>	Norway Maple	55,37 cm	Trunk splits at 0.8m high. Tree is co-dominant	Good	X		A
393		<i>Thuja occidentalis</i>	Eastern Cedar	26,20.5,18 cm	3 trunk multi trunk specimen- infested with Manitoba maple	Good	X		A
394		<i>Acer platanoides</i>	Norway Maple	46 cm	Good	Good	X		A
395		<i>Acer platanoides</i>	Norway Maple	26 cm	Good- surrounded by Ionicera	Good	X		A
396		<i>Malus sp.</i>	Apple	32,47 cm	2 trunk multi trunk specimen- 1 trunk hollowed- and broken	Fair		X	A
397		<i>Tilia sp.</i>	Linden	55 cm	Good	Good	X		D
398		<i>Acer saccharinum</i>	Silver Maple	81 cm	Good	Good	X		A
399		<i>Robinia pseudoacacia</i>	Black Locust	48 cm	20% Dead branches	Fair	X		D
400		<i>Pinus sylvestris</i>	Scot's Pine	22.5 cm	Trunk splits at 1.75m high and becomes co-dominant	Good	X		D
401		<i>Acer platanoides</i>	Norway Maple	30,39,16,43 cm	4 trunk multi trunk specimen- dead branch in centre of clump	Good	X		D
402		<i>Tilia americana</i>	Basswood	19,22,17,12,13, 18,21,17,17,16, 7<20 cm	17 trunk Thicket of Tilia	Good	X		D
403		<i>Robinia pseudoacacia</i>	Black Locust	74 cm	Good	Good	X		D
404		<i>Tilia sp.</i>	Linden	42,30 cm	Trunk splits at 1.4m ht. 2 trunk multi trunk specimen	Good	X		D
405		<i>Robinia pseudoacacia</i>	Black Locust	49, 74 cm	2 trunk multi trunk specimen	Good	X		D

### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.●	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
406		<i>Robinia pseudoacacia</i>	Black Locust	78 cm	Good	Good	X		D
407		<i>Acer platanoides</i>	Norway Maple	54 cm	Good	Good	X		D
408		<i>Pinus sylvestris</i>	Scot's Pine	35 cm	Good	Good	X		D
409		<i>Pinus sylvestris</i>	Scot's Pine	38 cm	Good	Good	X		D
410		<i>Pinus sylvestris</i>	Scot's Pine	32 cm	Good	Good	X		D
411		<i>Juglans nigra</i>	Black Walnut	44 cm	Good	Good	X		D
412		<i>Juglans nigra</i>	Black Walnut	58 cm	Good	Good	X		D
413		<i>Acer platanoides</i>	Norway Maple	22 cm	Good	Good	X		D
414		<i>Juglans nigra</i>	Black Walnut	52, 57 cm	Missing bark up in canopy- on property line of adjacent house	Fair	X		D
415		<i>Populus sp.</i>	Poplar	33 cm	Good- along property line of adjacent house	Good	X		D
416		<i>Acer sp.</i>	Maple	24 cm	Good- along property line of adjacent house	Good	X		D
417		<i>Acer sp.</i>	Maple	22.5 cm	Good- along property line of adjacent house	Good	X		D
418		<i>Populus sp.</i>	Poplar	59 cm	Good- along property line of adjacent house	Good	X		D
419		<i>Acer platanoides</i>	Norway Maple	23 cm	Good- along property line of adjacent house	Good	X		D
420		<i>Populus sp.</i>	Poplar	30 cm	Good- along property line of adjacent house	Good	X		D
421		<i>Populus sp.</i>	Poplar	32,45 cm	2 trunk multi trunk specimen- larger trunk is dead- along property line of adjacent	Fair		X	D

### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.•	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
422		<i>Pinus nigra</i>	Austrian Pine	32 cm	>70% dead	Poor		X	C
423		<i>Pinus nigra</i>	Austrian Pine	34 cm	Good	Good	X		A, C
424		<i>Pinus sylvestris</i>	Scot's Pine	32 cm	>70% dead	Poor		X	A
425		<i>Acer saccharinum</i>	Silver Maple	29, 35 cm	2 trunk multi trunk specimen	Good	X		A
426		<i>Pinus sylvestris</i>	Scot's Pine	30 cm	20% dead	Fair		X	A
427		<i>Acer saccharinum</i>	Silver Maple	45 cm	Good	Good	X		A
428		<i>Acer platanoides</i>	Norway Maple	55 cm	Good	Good	X		A
	10 trees not inventoried	<i>various</i>	<i>various</i>	<20 cm	Spruce and maple sp.- can be retained or relocated.	Good	X		A
429		<i>Thuja occidentalis</i>	Easter Cedar	33,20,22 cm	Good	Good	X		A
430		<i>Pinus nigra</i>	Austrian Pine	36 cm	Good	Good	X		A
431		<i>Juglans nigra</i>	Black Walnut	23, 15.5 cm	2 trunk multi trunk specimen	Good	X		D
432		<i>Malus sp.</i>	Apple	27, 25 cm	2 trunk multi trunk specimen-Low branching, suckers and buckthorn, poor branching	Fair	X		D
433		<i>Pinus sylvestris</i>	Scot's Pine	26 cm	>70% dead	Poor		X	B
434		<i>Pinus sylvestris</i>	Scot's Pine	34 cm	Good	Good	X		D
435		<i>Acer negundo</i>	Manitoba Maple	24 cm	Good	Good	X		D
436		<i>Thuja occidentalis</i>	Eastern Cedar	37, 34 cm	Good	Good	X		D

### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.●	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
437		<i>Salix sp.</i>	Willow	1.25m, 1.1m	Hollow wide, low branch, adjacent to a property with a house	Good		X	D
438		<i>Thuja occidentalis</i>	Eastern Cedar	25,25.5,17,22, 11 cm	Good	Good	X		A
439		<i>Tilia sp.</i>	Linden	21,21,22,22,22, 19,11,19,20,21 cm	10 trunk multi trunk specimen. Very large tree	Good	X		A
440		<i>Thuja occidentalis</i>	Eastern Cedar	29, 35 cm	2 trunk multi trunk specimen	Good	X		A
441		<i>Thuja occidentalis</i>	Eastern Cedar	24 cm	Good	Good	X		A
442		<i>Thuja occidentalis</i>	Eastern Cedar	16,10,22,19,24, 26,16,8 cm	Good	Good	X		A
443		<i>Thuja occidentalis</i>	Eastern Cedar	26,21,20,9 cm	Good	Good	X		A
444		<i>Tilia sp.</i>	Linden	45 cm	Good- suckering at base	Good	X		A
445		<i>Thuja occidentalis</i>	Eastern Cedar	21.5, 24.5 cm	Good	Good	X		A
446		<i>Acer platanoides</i>	Norway Maple	35.5 cm	Good	Good	X		A
447		<i>Acer negundo</i>	Manitoba Maple	33 cm	Good	Good	X		D
448		<i>Fraxinus sp.</i>	Ash	37.5 cm	Poor	Poor	X		A
449		<i>Pinus nigra</i>	Austrian Pine	39.5 cm	Good	Good	X		A
450		<i>Pinus sylvestris</i>	Scot's Pine	47.5 cm	Good	Good	X		D
451		<i>Pinus sylvestris</i>	Scot's Pine	76 cm	Good- dbh is indicative of trunk becoming co-dominant at this point	Good	X		D
452		<i>Malus sp.</i>	Apple	26,28,38,42 cm	1 dead trunk, 1 hollow trunk	Fair		X	A

### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.•	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
453		<i>Pinus sylvestris</i>	Scot's Pine	45 cm	Good	Good	X		D
454		<i>Pinus sylvestris</i>	Scot's Pine	76 cm	Good	Good	X		D
455		<i>Pinus sylvestris</i>	Scot's Pine	53 cm	Good	Good	X		D
456		<i>Malus sp.</i>	Apple	52,46 cm	1 dead trunk, 1 hollow trunk	Poor		X	A
457		<i>Fraxinus sp.</i>	Ash	57.5 cm	Dead	Poor		X	A
458		<i>Tsuga canadensis</i>	Eastern Hemlock	50.5 cm	Good	Good	X		D
459		<i>Acer saccharum</i>	Sugar Maple	60.5 cm	Good	Good	X		A
460		<i>Pinus nigra</i>	Austrian Pine	30 cm	Dead	Poor		X	A
461		<i>Pinus sylvestris</i>	Scot's Pine	28.5 cm	Becomes co dominant above dbh.	Good	X		A
462		<i>Thuja occidentalis</i>	Eastern White Cedar	43,50,24,20.5,1 2 cm	Good	Good	X		A
463		<i>Pinus sylvestris</i>	Scot's Pine	41 cm	Good	Good	X		A
464		<i>Pinus sylvestris</i>	Scot's Pine	43 cm	Good	Good	X		A
465		<i>Thuja occidentalis</i>	Eastern White Cedar	33,21,32,35,35, 11,12,9 cm	8 trunk multi trunk specimen	Good	X		A
466		<i>Pinus sylvestris</i>	Scot's Pine	50.5 cm	Good	Good	X		D
467		<i>Pinus sylvestris</i>	Scot's Pine	30 cm	Tree is surrounded by Buckthorn	Good	X		D
468		<i>Thuja occidentalis</i>	Eastern White Cedar	19.5,16,11 cm	3 trunk multi trunk specimen	Good	X		D

### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.●	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
469		<i>Thuja occidentalis</i>	Eastern White Cedar	20,21,16,11,12 cm	5 trunk multi trunk specimen- Retain as group	Good	X		D
470		<i>Thuja occidentalis</i>	Eastern White Cedar	21,19,10,9,11 cm	5 trunk multi trunk specimen- Retain as group	Good	X		D
471		<i>Ulmus americana</i>	American Elm	22 cm	Good- Retain as group	Good	X		D
472		<i>Pinus sylvestris</i>	Scot's Pine	42 cm	Good- Retain as group	Good	X		A
473		<i>Pinus nigra</i>	Austrian Pine	47.5 cm	Good- Retain as group	Good	X		A
474		<i>Acer platanoides</i>	Norway Maple	18,22,27 cm	3 trunk multi trunk specimen. Becomes co dominant at 0.8m ht. damage at base. Retain as part of group.	Fair		X	A
475		<i>Fraxinus sp.</i>	Ash	34 cm	Dead limbs	Poor		X	A
476		<i>Tilia cordata</i>	American Elm	39 cm	Good	Good	X		A
477		<i>Acer platanoides</i>	Norway Maple	32,20 cm	2 trunk multi trunk species. Becomes co dominant approx. 0.8 cm . Trunks twisted together	Good	X		A
478		<i>Acer Saccharinum</i>	Silver Maple	64.5 cm	Good	Good	X		A
479		<i>Tilia cordata</i>	Linden	33,27,28 cm	3 trunk multi trunk specimen	Good	X		A
480		<i>Tilia cordata</i>	Linden	33,35,39 cm	3 trunk multi trunk specimen	Good	X		A
481		<i>Pinus nigra</i>	Austrian Pine	45.5 cm	Good	Good	X		A
482		<i>Mystery Tree</i>	Unsure	44 cm	Good	Good	X		D
483		<i>Populus sp.</i>	Poplar	28,25,13 cm	Good	Good	X		D
484		<i>Ulmus americana</i>	American Elm	33,40 cm	Good, suckers of another tree at base	Good	X		D

### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.●	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
485		<i>Thuja occidentalis</i>	Eastern White Cedar	43,52,51,40 cm	4 trunk multi trunk specimen	Good	X		D
486		<i>Thuja occidentalis</i>	Eastern White Cedar	49, 53 cm	2 trunk multi trunk specimen	Good	X		A
487		<i>Malus sp.</i>	Apple	23,19,33,19 cm	1 trunks in good condition, 3 trunks in poor condition, large wound on trunk	Fair	X		A
488		<i>Malus sp.</i>	Apple	40,42 cm	2 trunks in good condition twisted together	Good	X		A
489		<i>Malus sp.</i>	Apple	25, 28 cm	2 trunk tree. A lot of bark removed	Poor		X	A
490		<i>Acer Saccharinum</i>	Silver Maple	63,26,26,13 cm	4 trunk multi trunk specimen. - 2 dead	Fair		X	A
491		<i>Malus sp.</i>	Apple	43 cm	Many hollows in trunk, bark removed	Fair		X	A
492		<i>Ulmus americana</i>	American Elm	40 cm	Good	Good	X		A
493		<i>Acer Saccharinum</i>	Silver Maple	20,20 cm	multi trunk specimen. Only 2 trunks on subject propert	Good	X		A
494		<i>Malus sp.</i>	Apple	33,28 cm	2 trunk multi trunk specimen	Good	X		A
495		<i>Malus sp.</i>	Apple	25,33 cm	2 trunk multi trunk - many suckers at base	Good	X		A
496		<i>Pinus strobus</i>	Eastern White Pine	47 cm	Good- retain as part of group	Good	X		A
497		<i>Pinus sylvestris</i>	Scot's Pine	29 cm	Good- retain as part of group	Good	X		A
498		<i>Pinus sylvestris</i>	Scot's Pine	30.5 cm	Good- retain as part of group	Good	X		A
499		<i>Pinus sylvestris</i>	Scot's Pine	37 cm	Good- retain as part of group	Good	X		A
500		<i>Pinus sylvestris</i>	Scot's Pine	22 cm	Many dead branches- retain as part of group	Fair		X	A



### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.●	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
501		<i>Pinus sylvestris</i>	Scot's Pine	22.5 cm	Many dead branches- retain as part of group	Fair		X	A
502		<i>Acer saccharum</i>	Sugar Maple	28,22,13 cm	3 trunk multi trunk	Good	X		A
503		<i>Pinus sylvestris</i>	Scot's Pine	28 cm	Good	Good	X		A
504		<i>Malus sp.</i>	Apple	31.5, 29cm	2 trunk multi trunk specimen	Good	X		A
505		<i>Malus sp.</i>	Apple	26 cm	Good- retain as part of group	Good	X		A
506		<i>Pinus sylvestris</i>	Scot's Pine	37 cm	Good- retain as part of group	Fair		X	A
507		<i>Malus sp.</i>	Apple	43 cm	Many hollows in trunk, bark removed Retain as part of group	Fair		X	A
508		<i>Pinus sylvestris</i>	Scot's Pine	23 cm	Good- retain as part of group	Good	X		A
509		<i>Malus sp.</i>	Apple	26 cm	Good	Good	X		A
510		<i>Malus sp.</i>	Apple	23.5 cm	Good	Good	X		A
511		<i>Acer saccharinum</i>	Silver maple	89, 62 cm	large 2 trunk multi trunk specimen	Good	X		A
512		<i>Salix sp.</i>	Willow	66 cm	Good	Good	X		A
513		<i>Salix sp.</i>	Willow	73 cm	Good	Good	X		A
514		<i>Acer saccharinum</i>	Silver maple	65 cm	Good	Good	X		A
515		<i>Acer saccharinum</i>	Silver maple	23,68,42,18 cm	4 trunk multi trunk tree	Good	X		D
516		<i>Tilia americana</i>	Basswood	59,43,47,62,44 cm	5 trunk multi trunk specimen- large	Good	X		D

**TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY**

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.●	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
517		<i>Picea sp.</i>	Spruce	20 cm	Good	Good	X		C
518		<i>Picea sp.</i>	Spruce	31.5 cm	Good	Good	X		C
519		<i>Picea sp.</i>	Spruce	32.5 cm	Good	Good	X		C
520		<i>Picea sp.</i>	Spruce	30 cm	Good	Good	X		C
521		<i>Malus sp.</i>	Apple	19,19,19,18,22, 14,14 cm	7 trunk multi trunk specimen- 2 trunks rotted	Fair		X	A
522		<i>Crataegus sp.</i>	Hawthorn	23,28,12 cm	4 trunk multi trunk specimen- hollows in trunk	Fair		X	A
523		<i>Pinus sylvestris</i>	Scot's Pine	42 cm	Good	Good	X		A
524		<i>Pinus sylvestris</i>	Scot's Pine	26 cm	Good- retain as group	Good	X		A
525		<i>Pinus sylvestris</i>	Scot's Pine	44 cm	Good- retain as group	Good	X		A
526		<i>Pinus sylvestris</i>	Scot's Pine	30 cm	Dead	Poor		X	A
527		<i>Pinus sylvestris</i>	Scot's Pine	24 cm	Dead	Poor		X	A
528		<i>Pinus sylvestris</i>	Scot's Pine	29 cm	Good	Good	X		C
529		<i>Juglans nigra</i>	Black Walnut	61 cm	Good	Good	X		A
530		<i>Picea pungens glauca</i>	Blue Spruce	35 cm	Good- retain as group	Good	X		A
531		<i>Picea pungens glauca</i>	Blue Spruce	23, 25 cm	becomes co-dominant at 1m retain as a group	Good	X		A
532		<i>Picea pungens glauca</i>	Blue Spruce	39 cm	Good- retain as group	Good	X		A

### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.●	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
533		<i>Juglans nigra</i>	Black Walnut	49.5 cm	Good	Good	X		C
534		<i>Ulmus americana</i>	American Elm	43.5 cm	Tree is at an angle, some dead branches	Good	X		D
535		<i>Juglans nigra</i>	Black Walnut	58 cm	Good	Good	X		C
536		<i>Unknown sp.</i>	Prunus??	34,29 cm	2 trunk multi trunk specimen. 50% bark removed at base. Surrounded by buckthorn- retain if possible	Fair		X	C
537		<i>Unknown sp.</i>	Prunus??	23 cm	7 trunk multi trunk specimen- 2 trunks rotted- surrounded by buckthorn. Retain if possible	Fair		X	C
538		<i>Robinia pseudoacacia</i>	Black Locust	50 cm	Good- borders property of adjacent house- retain if possible	Good	X		C
539		<i>Prunus serotina</i>	Black Cherry	35 cm	Good	Good	X		A
540		<i>Unknown sp.</i>	unsure	27, 33 cm	no bark, dead tree	Poor		X	A
541		<i>Pinus nigra</i>	Austrian Pine	27.5 cm	Good	Good	X		A
542		<i>Populus sp.</i>	Poplar	26 cm	Good- borders property of adjacent house- retain if possible	Good	X		A
543		<i>Populus sp.</i>	Poplar	21 cm	Good- borders property of adjacent house- retain if possible	Good	X		A
544		<i>Populus sp.</i>	Poplar	21 cm	Good- borders property of adjacent house- retain if possible	Good	X		A
545		<i>Populus sp.</i>	Poplar	25, 10 cm	2 trunks multi trunk specimen- smaller trunk dead- retain as part of wooded area	Fair		X	A
546		<i>Populus sp.</i>	Poplar	22,26 cm	2 trunk multi trunk specimen - retain as part of wooded area	Good	X		A
547		<i>Ulmus americana</i>	American Elm	79.5 cm	Good- borders property of adjacent house- retain if possible	Good	X		A
548		<i>Populus sp.</i>	Poplar	20.5 cm	Good- borders property of adjacent house- retain if possible	Good	X		A

### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.●	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
549		<i>Pinus sylvestris</i>	Scot's Pine	15, 20 cm	2 trunk multi trunk specimen. Good- as part of wooded area	Good	X		A
550		<i>Pinus sylvestris</i>	Scot's Pine	23.5 cm	Fair- Good as part of wooded area	Good	X		A
551		<i>Acer negundo</i>	Manitoba Maple	30.5 cm	Growing at a 45 degree angle	Good	X		A
552		<i>Acer negundo</i>	Manitoba Maple	29.5 cm	Growing at a 45 degree angle	Good	X		A
553		<i>Pinus sylvestris</i>	Scot's Pine	26 cm	Good- as part of wooded area	Good	X		A
554		<i>Acer negundo</i>	Manitoba Maple	30 cm	Growing at a 70 degree angle- Good as part of the wooded area	Good	X		A
555		<i>Acer negundo</i>	Manitoba Maple	32,30 cm	Growing at 30 degree angle- Good as part of the wooded area	Fair	X		A
556		<i>Picea</i>	Spruce	42 cm	Good- borders property of adjacent house- retain if possible	Good	X		A
557		<i>Picea sp.</i>	Spruce	39 cm	Good- borders property of adjacent house- retain if possible	Good	X		A
558		<i>Picea sp.</i>	Spruce	32 cm	Dead- but retain in wooded area	Dead		X	A
559		<i>Acer negundo</i>	Manitoba Maple	38, 26 cm	Good- as part of wooded area- retain next to property	Good	X		A
560		<i>Pinus sylvestris</i>	Scot's Pine	27 cm	Greater than 50% dead- Good as part of the wooded area	Fair		X	A
561		<i>Acer negundo</i>	Manitoba Maple	23.5, 16.9 cm	3 trunk multi trunk specimen- Mostly dead- Good as part of the wooded area	Poor		X	A
562		<i>Picea sp.</i>	Spruce	60 cm	Good- borders property of adjacent house- retain if possible	Good	X		A
563		<i>Acer negundo</i>	Manitoba Maple	38, 22, 36 cm	Growing at 45 degree angle, good as part of the wooded area	Good	X		A
564		<i>Acer negundo</i>	Manitoba Maple	41 cm	Good- borders property of adjacent house- retain if possible	Good	X		A

### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.●	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
565		<i>Picea sp.</i>	Spruce	46 cm	Good	Good	X		A
566		<i>Acer negundo</i>	Manitoba Maple	19,49 cm	Fair	Fair	X		A
567		<i>Pinus sylvestris</i>	Scot's Pine	36 cm	Good	Good	X		A
568		<i>Pinus sylvestris</i>	Scot's Pine	29,30 cm	Co- dominant	Good	X		A
569		<i>Acer negundo</i>	Manitoba Maple	25 cm	Trunk located on adjacent property	Good	X		C
570		<i>Acer negundo</i>	Manitoba Maple	25,17 cm	Trunk located on adjacent property	Good	X		C
571		<i>Salix pendula</i>	Weeping Willow	1.15m	Trunk straddles the property line	Good	X		D
572		<i>Pinus sylvestris</i>	Scot's Pine	29 cm	Dead	Poor		X	A
573		<i>Betula papyrifera</i>	Paperbark Birch	43 cm	Good- tree leans at an awkward angle	Good	X		A
574		<i>Acer negundo</i>	Manitoba Maple	37 cm	Trunk located on adjacent property- leans at 45 degree angle	Good	X		A
575		<i>Prunus serotina</i>	Black Cherry	71,22 cm	Two trunk multi trunk specimen- borders adjacent property, retain if possible	Good	X		A
576		<i>Acer negundo</i>	Manitoba Maple	21.5 cm	Good- borders adjacent property retain if possible	Good	X		A
577		<i>Prunus serotina</i>	Black Cherry	58 cm	Good	Good	X		D
578		<i>Malus sp.</i>	Apple	11,12,17,27.5 cm	4 trunk multi trunk specimen. 17 cm trunk is dead	Fair		X	D
579		<i>Pinus nigra</i>	Austrian Pine	40 cm	Dead	Poor		X	B
580		<i>Acer rubrum</i>	Red maple	30 cm	Good	Good	X		D

### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.♦	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
581		<i>Picea nigra</i>	Austrian Pine	43 cm	Dead	Poor		X	D
582		<i>Juglans nigra</i>	Black Walnut	102 cm	Good	Good	X		D
583		<i>Juglans nigra</i>	Black Walnut	37 cm	Good- on slope into valley	Good	X		D
584		<i>Juglans nigra</i>	Black Walnut	56 cm	Good- on slope into valley	Good	X		D
585		<i>Acer negundo</i>	Manitoba Maple	50 cm	Good- on slope into valley	Good	X		D
586		<i>Larix decidua</i>	Larch	57.5 cm	Good- retain as a group	Good	X		D
587		<i>Larix decidua</i>	Larch	40,12 cm	2 trunk multi trunk specimen- retain as a group.	Good	X		D
588		<i>Larix decidua</i>	Larch	52,28 cm	2 trunk multi trunk specimen- retain as a group.	Good	X		D
589		<i>Larix decidua</i>	Larch	9,37 cm	2 trunk multi trunk specimen- retain as a group.	Good	X		D
590		<i>Larix decidua</i>	Larch	51 cm	Good- retain as a group	Good	X		D
591		<i>Betula</i>	Birch	34 cm	Good	Good	X		D
592		<i>Betula</i>	Birch	29,31 cm	Good	Good	X		D
593		<i>Gleditsia</i>	Honeylocust	43 cm	Good	Good	X		D
594		<i>Acer saccharum</i>	Sugar Maple	36 cm	Good	Good	X		D
595		<i>Quercus macrocarpa</i>	Burr Oak	69.5 cm	Good	Good	X		D
596		<i>Betula</i>	Birch	33,33.5,18 cm	3 trunk multi trunk specimen	Good	X		D

### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.*	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
597		<i>Acer negundo</i>	Manitoba Maple	62 cm	Good	Good	X		D
598		<i>Acer negundo</i>	Manitoba Maple	33 cm	Good	Good	X		D
599		<i>Malus</i>	Apple sp.	23,26,19,21,21,22,13 cm	Good	Good	X		A
600		<i>Malus</i>	Apple sp.	59 cm	Good	Good	X		A
601		<i>Malus</i>	Apple sp.	34,42 cm	2 trunk multi trunk specimen. Larger trunk is hollow	Fair		X	A
602		<i>Pinus sylvestris</i>	Scot's Pine	38.5 cm	Good	Good	X		A
603		<i>Acer sp.</i>	Maple	27 cm	Good	Good	X		A
604		<i>Picea abies</i>	Spruce	24 cm	Good	Good	X		A
605		<i>Picea abies</i>	Spruce	21.5 cm	Good	Good	X		A
606		<i>Malus sp.</i>	Apple sp.	63.5 cm	Good	Good	X		A
607		<i>Picea sp.</i>	Spruce	20.5 cm	Good	Good	X		D
608		<i>Picea sp.</i>	Spruce	20.5 cm	Good	Good	X		D
609		<i>Tilia cordata</i>	Linden	43.5 cm	Good	Good	X		D
	3 trees not inventoried	<i>various</i>	varies	<20cm	3 Picea sp. - relocate if possible	Good	X		D
610		<i>Tilia sp.</i>	Linden	48.5 cm	Good	Good	X		D
611		<i>Picea glauca</i>	White spruce	39 cm	Good	Good	X		D

### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.●	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
612		<i>Fraxinus</i>	Ash	53.5 cm	Dead branches, suckering at base	Poor		X	B
613		<i>Picea sp.</i>	Spruce	36 cm	Good	Good	X		D
614		<i>Fraxinus</i>	Ash	45 cm	Dead branches,	Poor		X	B
615		<i>Picea sp.</i>	Spruce	32 cm	Good	Good	X		D
616		<i>Fraxinus</i>	Ash sp.	23,17,18,22,10,8 cm	6 trunk multi trunk specimen, dead branches	Poor		X	B
617		<i>Fraxinus</i>	Ash	44 cm	Many dead branches	Poor		X	D
618		<i>Malus sp.</i>	Apple sp.	21,20 cm	Good	Good	X		D
619		<i>Pinus nigra</i>	Austrian Pine	43.5 cm	Good	Good	X		A
620		<i>Tilia sp.</i>	Linden sp.	50.5 cm	Good	Good	X		D
621		<i>Tilia sp.</i>	Linden sp.	48 cm	Good	Good	X		D
622		<i>Tilia sp.</i>	Linden sp.	52 cm	Good	Good	X		A
623		<i>Acer platanoides</i>	Norway Maple	36.5 cm	Good	Good	X		A
624		<i>Pinus nigra</i>	Austrian Pine	41 cm	Good	Good	X		D
625		<i>Catalpa</i>	Catalpa	65 cm	Some evidence of damage at base of tree, looks to be in good condition	Good	X		D
626		<i>Tsuga canadensis</i>	Hemlock	19.5 cm	Good	Good	X		D
627		<i>Pinus nigra</i>	Austrian Pine	48 cm	Good	Good	X		D



### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.•	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
628		<i>Fraxinus</i>	Ash	40 cm	Poor	Poor		X	B
629		<i>Fraxinus</i>	Ash	36 cm	Poor	Poor		X	A
630		<i>Tilia sp.</i>	Linden sp.	43 cm	Good	Good	X		D
631		<i>Betula papyrifera</i>	Paperbark Birch	24,29,18,22 cm	4 trunk multi trunk specimen	Good	X		D
632		<i>Thuja sp.</i>	Cedar	38,37.5 cm	2 trunk multi trunk specimen	Good	X		A
633		<i>Thuja sp.</i>	Cedar	43,46 cm	2 trunk multi trunk specimen	Good	X		A
634		<i>Thuja sp.</i>	Cedar	32,27 cm	2 trunk multi trunk specimen	Good	X		A
635		<i>Thuja sp.</i>	Cedar	43 cm	Good	Good	X		A
636		<i>Tilia sp.</i>	Linden sp.	44.5 cm	Good	Good	X		D
637		<i>Tilia americana</i>	Basswood	50 cm	Good	Good	X		D
638		<i>Pinus nigra</i>	Austrian Pine	41.5 cm	Good	Good	X		A
639		<i>Picea abies</i>	Norway Spruce	44 cm	Good	Good	X		A
640		<i>Picea abies</i>	Norway Spruce	25 cm	Good	Good	X		A
641		<i>Pinus sylvestris</i>	Scot's Pine	28 cm	Dead	Poor		X	A
642		<i>Pinus sylvestris</i>	Scot's Pine	33 cm	Good	Good	X		A
643		<i>Picea sp.</i>	Spruce	48 cm	Good	Good	X		A

### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.●	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
644		<i>Pinus nigra</i>	Austrian Pine	35.5 cm	Good- retain as part of group	Good	X		A
645		<i>Pinus sylvestris</i>	Scot's Pine	38 cm	Good- retain as part of group	Good	X		A
646		<i>Picea abies</i>	Spruce	21 cm	Good- retain as part of group	Good	X		D
647		<i>Picea abies</i>	Spruce	28 cm	Good- retain as part of group	Good	X		D
648		<i>Pice abies</i>	Norway Spruce	23 cm	Good- retain as part of group	Good	X		D
	3 trees not inventoried	<i>various</i>	varies	<20 cm	3 Spruce < 20 cm dbh. Retain or relocate	Good	X		D
649		<i>Pinus sylvestris</i>	Scot's Pine	34,14 cm	Good	Good	X		D
650		<i>Populus</i>	Poplar sp.	74,56,63 cm	3 trunk multi trunk specimen	Good	X		D
	6 trees not inventoried	<i>various</i>	varies	<20 cm	6 trees <20 cm dbh. Retain or relocate	Good	X		D
651		<i>Tilia americana</i>	Basswood	31,22,29 cm	Good	Good	X		D
652		<i>Pinus sylvestris</i>	Scot's Pine	43 cm	Good	Good	X		D
653		<i>Tilia cordata</i>	Linden	47 cm	Good	Good	X		D
654		<i>Pinus sylvestris</i>	Scot's Pine	34.5 cm	Good	Good	X		D
655		<i>Picea pungens glacua</i>	Blue Spruce	28 cm	Good	Good	X		D
656		<i>Picea pungens glacua</i>	Blue Spruce	28 cm	Good	Good	X		D
657		<i>Picea pungens glacua</i>	Blue Spruce	34 cm	Good	Good	X		D

### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.●	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
658		<i>Pinus sylvestris</i>	Scot's Pine	26 cm	Good	Good	X		D
659		<i>Tilia cordata</i>	Linden	38, 28 cm	Good	Good	X		D
660		<i>Pinus sylvestris</i>	Scot's Pine	29 cm	Good	Good	X		D
661		<i>Ulmus americana</i>	American Elm	76 cm	Good	Good	X		D
662		<i>Tilia sp.</i>	Linden	30,31 cm	Good	Good	X		D
663		<i>Pinus sylvestris</i>	Scot's Pine	35 cm	Good	Good	X		D
664		<i>Tilia americana</i>	American Elm	20,27,21 cm	Good	Good	X		D
665		<i>Acer saccharinum</i>	Silver Maple	75 cm	Good	Good	X		D
666		<i>Pinus sylvestris</i>	Scot's Pine	29 cm	Good	Good	X		D
667		<i>Picea pungens glauca</i>	Blue Spruce	23 cm	Good- retain as a group	Good	X		D
668		<i>Picea abies</i>	Norway Spruce	24 cm	Good- retain as a group	Good	X		A
669		<i>Picea abies</i>	Norway Spruce	26 cm	Good- retain as a group	Good	X		A
670		<i>Picea abies</i>	Norway Spruce	28 cm	Good- retain as a group	Good	X		A
671		<i>Picea abies</i>	Norway Spruce	17, 18 cm	Co dominant- 2 trunk multi trunk species- Good retain as a group	Good	X		A
672		<i>Picea pungens glauca</i>	Blue Spruce	30 cm	Good- retain as a group- vine growing in tree, remove vine for tree vigor	Good	X		A
673		<i>Picea pungens glauca</i>	Blue Spruce	21 cm	Good- retain as a group	Good	X		A

### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.♦	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
674		<i>Tilia cordata</i>	Linden	22, 34.5 cm	Good	Good	X		A
675		<i>Fraxinus sp.</i>	Ash	34.5 cm	Very poor form, bark peeling, many dead branches	Poor		X	A
676		<i>Acer platanoides</i>	Norway Maple	30.5 cm	Good	Good	X		D
677		<i>Fraxinus sp.</i>	Ash	38.5 cm	Dead branches, broken limbs	Poor		X	B
678		<i>Fraxinus sp.</i>	Ash	30 cm	Dead branches, broken limbs	Poor		X	B
679		<i>Populus sp.</i>	Poplar	1.6m	2 trunk multi trunk specimen. Becomes 2 trunk at 1.6m ht. each trunk approx 65 cm dbh.	Good	X		D
680		<i>Tilia sp.</i>	Linden	54 cm	Good	Good	X		D
681		<i>Thuja sp.</i>	Eastern White Cedar	21,19,22,23,10,12 cm	6 trunk, multi trunk specimen	Good	X		D
682		<i>Thuja sp.</i>	Eastern White Cedar	20.5,20,24 cm	3 trunk multi trunk specimen	Good	X		D
683		<i>Thuja sp.</i>	Eastern White Cedar	29 cm	Good	Good	X		D
684		<i>Pinus sylvestris</i>	Scot's Pine	23 cm	Good	Good	X		D
685		<i>Thuja sp.</i>	Eastern White Cedar	16,15,16,12 cm	4 trunk multi trunk specimen- infested with buckthorn	Good	X		D
686		<i>Pinus sylvestris</i>	Scot's Pine	32 cm	Good	Good	X		D
687		<i>Picea abies</i>	Norway Spruce	40 cm	Good	Good	X		D
688		<i>Picea pungens glauca</i>	Blue Spruce	31 cm	Good	Good	X		D
689		<i>Fraxinus sp.</i>	Ash	26 cm	Fungus on bark, deteriorating	Fair		X	B

### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.●	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
690		<i>Acer saccharinum</i>	Silver Maple	106 cm	Multi trunk specimen trunks have grown together. Signs of included bar, broken	Good	X		A
691		<i>Acer platanoides</i>	Norway Maple	60 cm	Some evidence of split trunk, bark removal	Good	X		A
692		<i>Acer platanoides</i>	Norway Maple	54.5 cm	Good	Good	X		A
693		<i>Picea pungens glauca</i>	Blue Spruce	22 cm	Good- retain as part of group	Good	X		A
694		<i>Picea pungens glauca</i>	Blue Spruce	19.5 cm	Good- retain as part of group	Good	X		A
	3 trees not inventoried	<i>Picea sp.</i>	Spruce species	<20 cm	3 trees too small to inventory- but retain as part of a group. Relocate	Good	X		RELOCATE
695		<i>Pinus sylvestris</i>	Scot's Pine	24 cm	Many needles gone	Fair		X	C
696		<i>Pinus sylvestris</i>	Scot's Pine	22 cm	many needles gone	Fair		X	B
697		<i>Pinus sylvestris</i>	Scot's Pine	25.5 cm	Dead	Poor		X	A
698		<i>Picea pungens glauca</i>	Blue Spruce	30 cm	Good	Good	X		A
699		<i>Picea pungens glauca</i>	Blue Spruce	31 cm	Good	Good	X		A
700		<i>Pinus sylvestris</i>	Scot's Pine	23 cm	Good	Good	X		D
701		<i>Pinus sylvestris</i>	Scot's Pine	21 cm	Good	Good	X		D
702		<i>Picea abies</i>	Norway Spruce	45 cm	Good	Good	X		A
703		<i>Pinus sylvestris</i>	Scot's Pine	40.5 cm	Good	Good	X		A
704		<i>Picea abies</i>	Spruce species	34.5 cm	Good	Good	X		A

### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.*	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
705		<i>Acer saccharinum</i>	Silver Maple	30,31 cm	2 trunk multi trunk specimen	Good	X		A
706		<i>Acer platanoides</i>	Norway Maple	57 cm	Good	Good	X		A
707		<i>Thuja clump</i>	Eastern White Cedar	27,18,6,12,14,13,9 cm	7 trunk, multi trunk specimen	Good	X		A
708		<i>Thuja clump</i>	Eastern White Cedar	23,22,22 cm	Good	Good	X		A
709		<i>Pinus nigra</i>	Austrian Pine	25 cm	Good	Good	X		A
710		<i>Picea pungens glauca</i>	Spruce species	47 cm	Good	Good	X		A
711		<i>Pinus nigra</i>	Austrian Pine	22 cm	Good	Good	X		A
712		<i>Acer platanoides</i>	Norway Maple	44.5 cm	some broken limbs, and weed whacker damage at base	Fair	X		A
713		<i>Malus sp.</i>	Apple	46,45 cm	3 trunk multi trunk specimen- 1 trunk has been removed	Good	X		A
714		<i>Pinus nigra</i>	Austrian Pine	25,29 cm	Good	Good	X		A
715		<i>Acer platanoides</i>	Norway Maple	36.5 cm	Good	Good	X		A
716		<i>Pinus nigra</i>	Austrian Pine	46.5 cm	Good	Good	X		A
717		<i>Malus sp.</i>	Apple	23, 38 cm	2 trunk multi trunk specimen	Good	X		A
718		<i>Malus sp.</i>	Apple	26,24,24,24 cm	4 trunk multi trunk specimen- many broken branches	Fair		X	A
719		<i>Malus sp.</i>	Apple	48,29.5, 40 cm	3 trunk multi trunk specimen.	Good	X		A
720		<i>Acer negundo</i>	Manitoba Maple	21,14 cm	Low branching specimen	Good	X		A

### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.●	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
721		<i>Robinia pseudoacacia</i>	Black Locust	19 cm	Good	Good	X		D
722		<i>Salix</i>	Willow	41 cm	Good	Good	X		D
723		<i>Salix</i>	Willow	58 cm	Good	Good	X		D
724		<i>Salix</i>	Willow	54 cm	Good	Good	X		D
725		<i>Pinus sylvestris</i>	Scot's Pine	24 cm	Good	Good	X		D
726		<i>Picea pungens glauca</i>	Blue Spruce	31 cm	Good	Good	X		A
727		<i>Acer platanoides</i>	Norway Maple	69 cm	Good	Good	X		A
728		<i>Pinus sylvestris</i>	Scot's Pine	20 cm	Good	Good	X		D
729		<i>Pinus sylvestris</i>	Scot's Pine	33 cm	Good	Good	X		D
730		<i>Pinus sylvestris</i>	Scot's Pine	30 cm	Good	Good	X		D
731		<i>Populus sp.</i>	Poplar	59 cm	Good	Good	X		D
732		<i>Larix decidua</i>	Larch	34 cm	Good	Good	X		A
733		<i>Tilia sp</i>	Linden	42,46 cm	Good	Good	X		A
734		<i>Acer platanoides</i>	Norway Maple	38.5 cm	Good	Good	X		A
735		<i>Pinus sylvestris</i>	Scot's Pine	25 cm	Good	Good	X		A
736		<i>Pinus sylvestris</i>	Scot's Pine	25 cm	Good	Good	X		A

**TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY**

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.●	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
737		<i>Pinus sylvestris</i>	Scot's Pine	19.5 cm	Good	Good	X		A
738		<i>Pinus sylvestris</i>	Scot's Pine	35 cm	Good	Good	X		A
739		<i>Pinus sylvestris</i>	Scot's Pine	44 cm	Good	Good	X		A
740		<i>Pinus sylvestris</i>	Scot's Pine	21.5 cm	Good- retain as a group	Good	X		A
741		<i>Pinus sylvestris</i>	Scot's Pine	26 cm	Good- retain as a group	Good	X		A
742		<i>Larix decidua</i>	Larch	49 cm	Good- retain as a group	Good	X		A
743		<i>Acer platanoides</i>	Norway Maple	21.5 cm	Good	Good	X		D
744		<i>Malus sp.</i>	Apple	31,28,24 cm	2 trunk specimen, trunk splits again at 1m ht.	Good	X		D
745		<i>Larix decidua</i>	Larch	45.5 cm	Good	Good	X		D
746		<i>Larix decidua</i>	Larch	59 cm	Good	Good	X		D
747		<i>Larix decidua</i>	Larch	48 cm	Good	Good	X		D
748		<i>Acer saccharum</i>	Sugar Maple	10, 24 cm	2 trunk multi trunk specimen	Good	X		D
749		<i>Pinus nigra</i>	Austrian Pine	33 cm	Good	Good	X		D
750		<i>Pinus nigra</i>	Austrian Pine	21 cm	Good	Good	X		D
751		<i>Acer saccharum</i>	Sugar Maple	21.5 cm	Good	Good	X		D
752		<i>Pinus nigra</i>	Austrian Pine	30 cm	>90% dead canopy	Poor		X	B



### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.●	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
753		<i>Acer saccharum</i>	Sugar Maple	20.5 cm	Good	Good	X		D
	4 trees not inventoried	<i>Acer sp.</i>	Maple	<20 cm	4 trees <20 cm dbh- relocate if necessary	Good	X		D
754		<i>Acer platanoides</i>	Norway Maple	35 cm	Good	Good	X		D
755		<i>Picea pungens glauca</i>	Blue Spruce	36 cm	Good	Good	X		D
756		<i>Acer platanoides</i>	Norway Maple	26 cm	Good	Good	X		D
757		<i>Acer sp.</i>	Maple	22 cm	Good	Good	X		D
	5 trees not inventoried	<i>Acer sp.</i>	Maple	<20 cm	All Maples <20 cm dbh. Relocate if possible	Good	X		RELOCATE
758		<i>Pinus sylvestris</i>	Scot's Pine	23 cm	Good	Good	X		D
759		<i>Acer saccharinum</i>	Silver Maple	23 cm	Good	Good	X		A
760		<i>Acer platanoides</i>	Norway Maple	24 cm	Good	Good	X		D
761		<i>Malus sp.</i>	Apple	30,30,19 cm	3 trunk multi trunk specimen, 1 trunk bark removed.	Good	X		D
762		<i>Pinus sylvestris</i>	Scot's Pine	39 cm	Good	Good	X		D
763		<i>Pinus sylvestris</i>	Scot's Pine	40 cm	Good	Good	X		D
764		<i>Malus sp.</i>	Apple	42 cm	Trunk broken	Fair	X		D
765		<i>Malus sp.</i>	Apple	44.5 cm	Good	Good	X		D
766		<i>Pinus sylvestris</i>	Scot's Pine	34.5 cm	Good	Good	X		D

**TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY**

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.*	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
767		<i>Pinus sylvestris</i>	Scot's Pine	39.5 cm	Good	Good	X		D
768		<i>Acer platanoides</i>	Norway Maple	41 cm	Tree straddles property line	Good	X		C
769		<i>Tilia americana</i>	Basswood	71, 78 cm	large 2 trunk specimen, straddles property line	Good	X		C
770		<i>Ulmus americana</i>	Elm?	31 cm	Good	Good	X		D
771		<i>Malus sp.</i>	Apple	31,23,18 cm	3 trunk multi trunk specimen.	Good	X		D
772		<i>Tilia americana</i>	Basswood	45,48,24,52,23 cm	5 trunk multi trunk specimen	Good	X		D
773		<i>Picea pungens glauca</i>	Blue Spruce	30 cm	Good	Good	X		D
774		<i>Malus sp.</i>	Apple	34, 22 cm	2 trunk multi trunk specimen	Good	X		D
775		<i>Malus sp.</i>	Apple	30,31 cm	2 trunk multi trunk specimen	Good	X		D
776		<i>Malus sp.</i>	Apple	20 cm	Good	Good	X		D
777		<i>Craetagus sp.</i>	Hawthorne	27, 31 cm	Good	Good	X		D
778		<i>Malus sp.</i>	Malus	33.5 cm	Good	Good	X		D
	6 trees not inventoried	<i>various</i>	varies	<20 cm	5, acer, and 1 spruce <20 cm	Good	X		RELOCATE
779		<i>Tilia americana</i>	Basswood	29,54 cm	2 trunk multi trunk specimen	Good	X		D
780		<i>Ulmus americana</i>	American Elm	66 cm	Good	Good	X		D
781		<i>Ulmus americana</i>	American Elm	24 cm	Good	Good	X		D

### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.*	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
782		<i>Malus sp.</i>	Apple	31 cm	Mostly dead, hollow, broken branches	Poor		X	B
783		<i>Tilia americana</i>	Basswood	30.5,23,46 cm	3 trunk multi trunk specimen.	Good	X		D
784		<i>Fraxinus sp.</i>	Ash	35 cm	Mostly dead, hollow, broken branches	Poor		X	B
785		<i>Fraxinus sp.</i>	Ash	32 cm	Good	Fair		X	B
786		<i>Fraxinus sp.</i>	Ash	23,24 cm	2 trunk multi trunk specimen	Fair		X	B
	10 trees not inventoried	<i>Acer</i>	Maple spl	<20 cm	Good- relocate if possible	Good	X		RELOCATE
787		<i>Rhamnus cathartica</i>	Buckthorn	23,15,14,19 cm	Invasive species	Fair		X	B
788		<i>Tilia americana</i>	Basswood	41,17 cm	2 trunk multi trunk specimen	Good	X		D
789		<i>Acer saccharum</i>	Sugar Maple	49 cm	Good	Good	X		D
790		<i>Tilia americana</i>	Basswood	35,37,50,53 cm	4 trunk multi trunk specimen	Good	X		D
791		<i>Ulmus americana</i>	Basswood	51 cm	Good	Good	X		D
	3 trees not inventoried	<i>various</i>	varies	<20 cm	2 spruce, and 1 abies.	Good	X		RELOCATE
792		<i>Malus sp.</i>	Apple	69 cm	Good	Good	X		D
793		<i>Species?</i>	Unknown	36 cm	Dead	Poor		X	B
794		<i>Acer negundo</i>	Manitoba Maple	21 cm	Good- screens adjacent property	Good	X		D
795		<i>Acer negundo</i>	Manitoba Maple	28, 29 cm	Good- screens adjacent property	Good	X		D

### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.●	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
796		<i>Acer negundo</i>	Manitoba Maple	38 cm	Good- screens adjacent property	Good	X		D
797		<i>Acer negundo</i>	Manitoba Maple	39, 37 cm	2 trees close together. - screens adjacent property	Good	X		D
	4 trees not inventoried	<i>various</i>	varies	<20cm	2 maple, 1 ginkgo, 1 Gleditsia, relocate if possible	Good	X		RELOCATE
798		<i>Acer sp.</i>	Maple sp.	22.5 cm	Good	Good	X		A
799		<i>Salix sp.</i>	Willow	1.36m	2 trunk multi trunk. Becomes two trunk at 1.6m	Fair		X	A
800		<i>Salix sp.</i>	Willow	79,77,76 cm	3 trunk multi trunk specimen. Trunk becomes multi trunk at 1.0m	Good	X		A
801		<i>Picea abies</i>	Spruce	20 cm	Good- screens adjacent property	Good	X		D
802		<i>Picea abies</i>	Spruce	23 cm	>60% dead- screens adjacent property	Poor		X	B
803		<i>Picea abies</i>	Spruce	23 cm	Good- screens adjacent property	Good	X		D
804		<i>Picea abies</i>	Spruce	23 cm	Good- screens adjacent property	Good	X		D
805		<i>Picea abies</i>	Spruce	22 cm	Good- screens adjacent property	Good	X		D
806		<i>Picea abies</i>	Spruce	22 cm	Good- screens adjacent property	Good	X		D
	5 trees not inventoried	<i>Picea sp.</i>	Spruce	<20 cm	Part of group above- screens adjacent property	Good	X		D
807		<i>Salix pendula</i>	Weeping Willow	95 cm	Good- some broken branches in canopy- adjacent to wet pocket	Good	X		D
808		<i>Salix pendula</i>	Weeping Willow	81 cm	Good- adjacent to wetland	Good	X		D
809		<i>Salix pendula</i>	Weeping Willow	84 cm	Good- adjacent to wetland	Good	X		D

**TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY**

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.*	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
810		<i>Salix pendula</i>	Weeping Willow	96 cm	Some large limbs broken off dead wood in canopy	Good	X		A
811		<i>Salix pendula</i>	Weeping Willow	95 cm	many dead branches	Poor		X	D
812		<i>Salix pendula</i>	Weeping Willow	68 cm	Good	Good	X		D
813		<i>Salix pendula</i>	Weeping Willow	82 cm	Good	Good	X		D
814		<i>Thuja sp.</i>	Eastern White Cedar	25, 28, 25 cm	3 trunk multi trunk specimen- retain as part of group	Good	X		D
815		<i>Thuja sp.</i>	Eastern White Cedar	26,19,20,11 cm	4 trunk multi trunk specimen- retain as part of group	Good	X		D
816		<i>Thuja sp.</i>	Eastern White Cedar	32 cm	Good- retain as part of group	Good	X		D
817		<i>Thuja sp.</i>	Eastern White Cedar	20,19 cm	2 trunk multi trunk specimen- retain as part of group	Good	X		D
818		<i>Thuja sp.</i>	Eastern White Cedar	22,8,12 cm	Good- retain as part of group	Good	X		D
819		<i>Thuja sp.</i>	Eastern White Cedar	20,19 cm	Good	Good	X		D
820		<i>Thuja sp.</i>	Eastern White Cedar	24 cm	Good	Good	X		D
821		<i>Thuja sp.</i>	Eastern White Cedar	55 cm	Good	Good	X		D
822		<i>Thuja sp.</i>	Eastern White Cedar	35,22, 27,42 cm	4 trunk multi trunk specimen.	Good	X		D
823		<i>Malus sp.</i>	Apple	22,18,19,14,7,10,11,12 cm	8 trunk multi trunk specimen	Good	X		D
824		<i>Thuja sp.</i>	Eastern White Cedar	31,21 cm	2 trunk multi trunk specimen- retain as part of group	Good	X		D
825		<i>Thuja sp.</i>	Eastern White Cedar	50 cm	Good- retain as part of group	Good	X		D

### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.●	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
826		<i>Thuja sp.</i>	Eastern White Cedar	42,30,31,30,20 cm	5 trunk multi trunk specimen- retain as part of group	Good	X		A
827		<i>Thuja sp.</i>	Eastern White Cedar	36,42 cm	2 trunk multi trunk specimen- retain as part of group	Good	X		A
828		<i>Thuja sp.</i>	Eastern White Cedar	40 cm	Good- retain as part of group	Good	X		A
829		<i>Thuja sp.</i>	Eastern White Cedar	43,36 cm	2 trunk multi trunk specimen- retain as part of group	Good	X		A
830		<i>Acer saccharinum</i>	Silver Maple	48 cm	Good	Good	X		A
831		<i>Fraxinus sp.</i>	Ash	42 cm	dead limbs	Fair		X	A
832		<i>Picea abies</i>	Spruce	33 cm	Good	Good	X		A
833		<i>Tilia cordata</i>	Linden	33 cm	Good	Good	X		A
834		<i>Acer saccharinum</i>	Silver Maple	44 cm	Good	Good	X		A
835		<i>Picea pungens</i>	Spruce	33 cm	Good	Good	X		A
836		<i>Acer saccharinum</i>	Silver Maple	24 cm	Good	Good	X		A
837		<i>Picea pungens</i>	Spruce	29 cm	Good	Good	X		A
838		<i>Acer saccharinum</i>	Silver Maple	26 cm	Good	Good	X		A
839		<i>Picea pungens</i>	Spruce	36 cm	Good	Good	X		A
840		<i>Fraxinus sp.</i>	Ash	45 cm	dead limbs	Fair		X	A
841		<i>Acer saccharinum</i>	Silver Maple	11,21,16.5,7 cm	4 trunk multi trunk specimen becomes multi trunk at 1m dbh	Good	X		A

### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.●	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
842		<i>Picea sp</i>	Spruce	33 cm	Good	Good	X		A
843		<i>Acer saccharinum</i>	Silver Maple	45.5 cm	Good	Good	X		A
844		<i>Picea sp.</i>	Spruce	34 cm	Good	Good	X		A
845		<i>Fraxinus sp.</i>	Ash	42 cm	dead limbs	Fair	X		A
846		<i>Tilia cordata</i>	Linden	34 cm	Good	Good	X		A
847		<i>Picea</i>	Spruce	54 cm	trunk damaged on one side	Fair	X		A
848		<i>Picea pungens</i>	Spruce	41 cm	Good	Good	X		A
849		<i>Fraxinus sp.</i>	Ash	40.5 cm	dead limbs	Fair		X	A
850		<i>Fraxinus sp.</i>	Ash	48 cm	dead limbs	Fair		X	A
851		<i>Gleditsia</i>	Honeylocust	27,13,11 cm	Becomes multi trunk at 1.2m ht.	Good	X		A
852		<i>Picea</i>	Spruce	38 cm	Good	Good	X		A
853		<i>Pinus sylvestris</i>	Scot's Pine	26,22 cm	2 trunk multi trunk specimen- dead	Poor		X	A
854		<i>Picea sp.</i>	Spruce	44 cm	Good	Good	X		A
855		<i>Fraxinus sp.</i>	Ash	35 cm	dead limbs	Fair		X	A
856		<i>Picea sp.</i>	Spruce	29 cm	Dead	Poor		X	A
857		<i>Fraxinus sp.</i>	Ash	31 cm	dead limbs	Poor		X	A

### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.●	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
858		<i>Picea sp.</i>	Spruce	29 cm	Dead	Poor		X	A
859		<i>Acer saccharinum</i>	Silver Maple	42.5 cm	Good	Good	X		A
860		<i>Pinus sylvestris</i>	Scot's Pine	33.5 cm	>70% dead	Fair		X	A
861		<i>Pinus sylvestris</i>	Scot's Pine	33.5 cm	dead	Poor		X	A
862		<i>Fraxinus sp.</i>	Ash	36 cm	dead limbs	Poor		X	A
863		<i>Pinus sylvestris</i>	Scot's Pine	28 cm	Good	Good	X		C
864		<i>Betula sp.</i>	Birch	23,18.5 cm	2 trunk multi trunk specimen.	Good	X		A
865		<i>Pinus sylvestris</i>	Scot's Pine	23 cm	50% dead	Poor		X	A
866		<i>Acer saccharinum</i>	Silver Maple	28,28 cm	2 trunk multi trunk specimen	Good	X		A
867		<i>Picea abies</i>	Spruce	36 cm	Good	Good	X		A
868		<i>Fraxinus sp.</i>	Ash	34 cm	Good	Good	X		A
869		<i>Pinus sylvestris</i>	Scot's Pine	40 cm	Good	Good	X		A
870		<i>Betula sp.</i>	Birch	20.5, 21 cm	Good	Good	X		A
871		<i>Picea abies</i>	Norway Spruce	41 cm	Good	Good	X		C
	1 tree not inventoried	<i>Acer sp.</i>	Maple	<20 cm	Good- relocate if possible	Good	X		RELOCATE
872		<i>Fraxinus sp.</i>	Ash	44 cm	dead limbs	Fair		X	B



**TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY**

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.●	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
873		<i>Populus</i>	Poplar	78.5cm	Good	Good	X		A
874		<i>Picea abies</i>	Norway Spruce	38 cm	Good	Good	X		A
875		<i>Fraxinus sp.</i>	Ash	47 cm	trunk damage at base	Fair		X	B
876		<i>Pinus sylvestris</i>	Scot's Pine	28 cm	Good	Good	X		A
877		<i>Pinus nigra</i>	Austrian Pine	32 cm	Good	Good	X		D
878		<i>Picea abies</i>	Norway Spruce	30,31 cm	2 trunks merged and separate at 1.6m ht.	Good	X		C
879		<i>Pinus sylvestris</i>	Scot's Pine	31 cm	Dead	Poor		X	C
880		<i>Fraxinus sp.</i>	Ash	27, 29 cm	2 trunk multi trunk specimen	Fair		X	A
881		<i>Picea abies</i>	Norway Spruce	41.5 cm	Good	Good	X		C
882		<i>Picea pungens</i>	Spruce	31 cm	Good	Good	X		A
883		<i>Acer platanoides</i>	Norway Maple	40 cm	Good	Good	X		A
884		<i>Fraxinus sp.</i>	Ash	15,12,10,10,16 cm	5 trunk multi trunk specimen- bark all peeled off	Poor		X	B
885		<i>Picea abies</i>	Norway Spruce	52.5 cm	Good	Good	X		A
886		<i>Acer platanoides</i>	Norway Maple	56 cm	Good	Good	X		A
887		<i>Fraxinus sp.</i>	Ash	52 cm	Fair- dead limbs	Fair		X	B
888		<i>Pinus sylvestris</i>	Scot's Pine	38 cm	Dead	Poor		X	B

### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.●	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
889		<i>Robinia pseudoacacia</i>	Black Locust	65 cm	Some dead branches in crown	Fair	X		A
890		<i>Robinia pseudoacacia</i>	Black Locust	58 cm	Split in trunk, some dead branches	Fair	X		A
891		<i>Robinia pseudoacacia</i>	Black Locust	23,26,42,18,17 cm	5 trunk multi trunk specimen- bark is peeling, included bark on trunk	Fair		X	A
892		<i>Fraxinus sp.</i>	Ash	37 cm	Some dead branches in crown	Fair	X		A
893		<i>Fraxinus sp.</i>	Ash	41 cm	Some dead branches in crown	Fair	X		A
894		<i>Pinus sylvestris</i>	Scot's Pine	32 cm	Good	Good	X		A
895		<i>Pinus sylvestris</i>	Scot's Pine	36 cm	Good	Good	X		A
896		<i>Tilia americana</i>	Basswood	44,20,17 cm	3 trunk multi trunk specimen	Good	X		A
897		<i>Pinus sylvestris</i>	Scot's Pine	28 cm	Dead	Poor		X	B
898		<i>Fraxinus sp.</i>	Ash	28 cm	Dead	Poor		X	B
899		<i>Pinus sylvestris</i>	Scot's Pine	25 cm	Some dead branches in crown	Fair		X	B
900		<i>Acer saccharinum</i>	Silver Maple	39 cm	Good	Good	X		D
901		<i>Pinus sylvestris</i>	Scot's Pine	32 cm	Good	Good	X		A
902		<i>Fraxinus sp.</i>	Ash	47 cm	Fair- dead limbs	Fair		X	B
903		<i>Thuja sp.</i>	Eastern White Cedar	21.5,18,14,14,11 cm	5 trunk multi trunk specimen	Good	X		D
904		<i>Robinia pseudoacacia</i>	Black Locust	26,32,20.5 cm	1 trunk dead, 2 others missing bark	Poor		X	B

**TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY**

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.●	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
905		<i>Ulmus americana</i>	American Elm	56.5 cm	Good	Good	X		A
906		<i>Fraxinus sp.</i>	Ash	39.5, 38 cm	Some dead branches in crown	Fair		X	B
907		<i>Pinus sylvestris</i>	Scot's Pine	52 cm	Good	Good	X		D
908		<i>Pinus sylvestris</i>	Scot's Pine	32 cm	Good	Good	X		A
909		<i>Pinus sylvestris</i>	Scot's Pine	22 cm	Dead	Poor		X	B
910		<i>Pinus sylvestris</i>	Scot's Pine	29 cm	Dead	Poor		X	B
911		<i>Pinus sylvestris</i>	Scot's Pine	35 cm	Dead	Poor		X	B
912		<i>Pinus sylvestris</i>	Scot's Pine	36 cm	Dead	Poor		X	B
913		<i>Pinus sylvestris</i>	Scot's Pine	39 cm	Dead	Poor		X	B
914		<i>Juglans nigra</i>	Black Walnut	23.5 cm	Good	Good	X		A
915		<i>Fraxinus sp.</i>	Ash	24 cm	Some dead branches in crown	Fair		X	B
916		<i>Fraxinus sp.</i>	Ash	23 cm	Multi trunk above the dbh height	Fair		X	B
917		<i>Robinia pseudoacacia</i>	Black Locust	46,13,10 cm	Bark removed, dead branches in crown	Poor		X	B
918		<i>Pinus sylvestris</i>	Scot's Pine	33 cm	Good	Good	X		A
919		<i>Fraxinus sp.</i>	Ash	30 cm	Good	Fair		X	A
920		<i>Fraxinus sp.</i>	Ash	43 cm	Some dead branches in crown	Fair		X	A

### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.●	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
921		<i>Fraxinus sp.</i>	Ash	56.5 cm	Deep split in trunk- does not look stable	Poor		X	B
922		<i>Pinus sylvestris</i>	Scot's Pine	32 cm	Good	Good		X	A
923		<i>Fraxinus sp.</i>	Ash	48 cm	Some dead branches in crown	Poor		X	B
924		<i>Tilia americana</i>	Linden	31 cm	Good	Good	X		A
925		<i>Picea abies</i>	Spruce	44 cm	Good	Good	X		A
926		<i>Tilia americana</i>	Linden	62 cm	tree becoms multi trunk at 1.4m	Good	X		A
927		<i>Fraxinus sp.</i>	Ash	53.5 cm	Some dead branches in crown	Poor		X	B
928		<i>Fraxinus sp.</i>	Ash	40 cm	Some dead branches in crown	Poor		X	B
929		<i>Picea abies</i>	Spruce	33.5 cm	Good	Good	X		A
930		<i>Picea abies</i>	Spruce	?	Good	Good	X		A
931		<i>Tilia americana</i>	Linden	34,23,19,11,19.5,17,17,15 cm	Some dead branches in crown	Good	X		A
932		<i>Rhamnus cathartica</i>	Buckthorn	22,20,8,7,5 cm	Multi trunk specimen- Invasive species	Fair		X	B
933		<i>Gleditsia</i>	Honeylocust	31,5,26 cm	3 trunk multi trunk specimen	Good	X		A
934		<i>Pinus sylvestris</i>	Scot's Pine	34 cm	Good	Good	X		BLOCK 224
	trees not inventoried	<i>Various</i>	Varies	<20 cm	6 white pine, 8 spruce, 1 red oak too small to inventory- relocate if possible	Good	X		BLOCK 224
935		<i>Pinus nigra</i>	Austrian Pine	34 cm	Good	Good	X		BLOCK 224

### TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY

**Recommendation Categories**

A - Removal required due to conflict with proposed development and grading

B - Removal recommended due to health and rating of species

C - Tree to be retained due to location outside limit of development

D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.●	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
936		<i>Acer platanoides</i>	Norway Maple	26.5,40 cm	2 trunk multi trunk specimen, codominant at 1.0m ht.	Good	X		BLOCK 224
	trees not inventoried	<i>Acer platanoides</i>	Norway Maple	<20 cm	4 Maples less than 20 cm- relocate if possible	Good		X	BLOCK 224
937		<i>Salix sp.</i>	Willow	1.83m	Some dead branches in crown becomes co dominant at 2m high. Prune dead	Good	X		BLOCK 224
	trees not inventoried	<i>Acer sp.</i>	Maple sp.	<20 cm	Maples less than 20 cm- relocate if possible	Good	X		BLOCK 224
938		<i>Salix sp.</i>	Willow	1.2m	Prune dead wood from canopy	Good	X		BLOCK 224
	trees not inventoried	<i>Picea pungens glauca</i>	Blue Spruce	<20 cm	Good- relocate if possible	Good	X		BLOCK 224
939		<i>Acer platanoides</i>	Norway Maple	36 cm	Good	Good	X		BLOCK 224
940		<i>Pinus nigra</i>	Austrian Pine	51 cm	Good	Good	X		BLOCK 224
941		<i>Pinus nigra</i>	Austrian Pine	53 cm	Good	Good	X		BLOCK 224
942		<i>Pinus nigra</i>	Austrian Pine	51 cm	Good	Good	X		BLOCK 224
	trees not inventoried	<i>Various</i>	Varies	<20cm	1 Quercus robur, 1 Picea <20 cm- relocate if possible	Good	X		BLOCK 224
943		<i>Acer platanoides</i>	Norway Maple	47.5 cm	Good	Good	X		BLOCK 224
944		<i>Acer platanoides</i>	Norway Maple	38 cm	Good	Good	X		BLOCK 224
945		<i>Pinus nigra</i>	Austrian Pine	31.5 cm	40% dieback	Fair	X		BLOCK 224
946		<i>Pinus nigra</i>	Austrian Pine	32 cm	Good	Good	X		BLOCK 224
	trees not inventoried	<i>Various</i>	Varies	<20 cm	2 Quercus rubrua	Good	X		BLOCK 224

**TREE INVENTORY AND ASSESSMENT REPORT WITHIN DEVELOPMENT PROPERTY**

**Recommendation Categories**

- A - Removal required due to conflict with proposed development and grading
- B - Removal recommended due to health and rating of species
- C - Tree to be retained due to location outside limit of development
- D - Tree to be retained where proposed grading allows

Tree Number	Location Within Development Property	Species		Approx. Size (m dia.) D.B.H.●	Condition / Comments	Rating	Potential For Preservation		Recommendations
		Botanical Name	Common Name				High	Low	
947		<i>Pinus nigra</i>	Austrian Pine	37.5 cm	Good	Good	X		BLOCK 224
	trees not inventoried	<i>Various</i>	Varies	<20 cm	1 Quercus rubra, 1 Acer platanoides, 4 Multi trunk lg shrub- relocate if possible	Good	X		BLOCK 224
948		<i>Fraxinus</i>	Ash	27 cm	Many dead branches/ limbs	Poor		X	BLOCK 224
949		<i>Picea pungens glauca</i>	Blue Spruce	40 cm	Good	Good	X		BLOCK 224
		<i>Various</i>	Varies	<20cm	4 Syringa reticulata, 3 Pinus strobus, 4 Picea pungens glauca, 8 Thuja occidentalis <20 cm. - Relocate if possible.	Good	X		BLOCK 224